

Road Conditions December 2011

N1

National Route	N1
Section	Old Oak Interchange to Worcester
Distance	82.44 km
Description	Two-lane dual carriageway with paved shoulders.
Condition of Road	Fair to Good.
Comments	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Maintenance	Heuppschenne Lekay 082 782 9155

National Route	N1
Section	Worcester to Laingsburg
Distance	156 km
Description	Single carriageway with paved shoulders. The road through Hex River Pass is a four-lane dual carriageway (four km) with an arrestor bed in the south-bound direction before the hairpin curve known as "Spookdraai". Stopping places are provided at regular intervals.
Condition of Road	Good.
Comments	A compulsory stop, manned by the Provincial Traffic Department, is in operation \pm five km south of Touws River. An unmanned compulsory stop for heavy vehicles is also in operation on the south-bound carriageway in Hex River Pass. Motorists should also be alert to pedestrians and/or stray animals just north of De Doorns. Motorists should also be alert to hawkers selling alongside the road. It is illegal to stop and buy from the sellers.
Duration of Work	Ongoing
Contact for Routine Maintenance	Carl Roberts 082 468 0241

National Route	N1
Section	Laingsburg to Leeu-Gamka
Distance	124 km
Description	Single carriageway with paved shoulders. Stopping places are provided at regular intervals.
Condition of Road	Good.
Comments	Construction works are in progress north of Laingsburg. Motorists can encounter up to three manually controlled Stop/Go sections during the day and traffic signal units at night with waiting periods on average 10 minutes. "Kanniedood" safety project is in operation on this section of road. A compulsory stop, manned by the Provincial Traffic Department, is in operation \pm 15 km south of Leeu-Gamka. Motorists should be alert to pedestrians and/or stray animals crossing the road in the vicinity of Leeu-Gamka.
Duration of Work	May 2011 until December 2012
Contact for Routine Maintenance	Jerome Buys 082 328 9422

National Route	N1
Section	Leeu-Gamka to Beaufort-West
Distance	75 km
Description	Single carriageway with paved shoulders. Stopping places are provided at regular intervals.
Condition of Road	Good.
Comments	Routine road maintenance teams may be encountered. Motorists should also be alert to pedestrians and/or stray animals in Beaufort-West.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Jerome Buys 082 328 9422

National Route	N1
Section	Beaufort-West to Three-Sisters
Distance	97 km
Description	Single carriageway with paved shoulders. Stopping places are provided at regular intervals.
Condition of Road	Good.
Comments	Routine road maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Maintenance	Jerome Buys 082 328 9422

National Route	N1
Section	Three-Sisters to Colesberg
Distance	236 km
Description	Single carriageway with paved shoulders. Stopping places are provided at regular intervals.
Condition of Road	Fair to Good.
Comments	Construction works are in progress between Hanover and Colesberg. Motorists can encounter up to two manually controlled Stop/Go sections during the day and possible traffic signal units at night with waiting periods on average 10 minutes.
Duration of Work	September 2011 until May 2012
Contact for Routine Maintenance	Dewet Lodewyk 083 383 8174

National Route	N1
Section	Orange River (Provincial Boundary) to Bloemfontein (Sydenham Interchange)
Distance	175 km
Description	Predominantly, a two lane single carriageway. The full length of the road has wide paved shoulders.
Condition of Road	Fair to satisfactory.
Comments	Repair work with two daytime stop/go controls will be operational between Orange River and Springfontein until 15 December 2011. Road construction is being undertaken between Fonteinjie (Section 14, km39) and Wurasoord (Section 14, km90.2). Three Stop/Go controls are in place during the day and at night, with expected delays of up to 20 minutes each.
Duration of Work	Construction / Rehabilitation activity is scheduled for completion March 2013.
Contact for Routine Road Maintenance	Potgieter CJ (Pottie) 082 566 7301

National Route	N1
Section	Bloemfontein to Kroonstad
Distance	189 km
Description	Around Bloemfontein and extending northwards for some 15km, the road is a four-lane dual carriageway with wide paved shoulders. Thereafter it reduces to a four-lane single carriageway for the next 20kms.; otherwise it is a two-lane single carriageway with paved shoulders and passing lanes on steep gradients. The last 10 km, known as the Kroonstad Bypass, is a four-lane dual carriageway.
Condition of Road	Generally good.
Comments	A contract for the repair and reseal between Zandkraal (just south of Verkeerdevlei toll plaza) and Winburg is in progress. Work will be undertaken in half-widths with 2-way traffic accommodated for the majority of contract duration. No traffic accommodation measures will be in place from 15 December 2011 to 8 January 2012. An improvement contract through Ventersburg commenced in October 2011. The road will be realigned and traffic will be accommodated through parallel roads adjacent to the N1. Ad-hoc Stop/Go controls will also be in place until 15 December 2011. Motorists should be alert to pedestrian and heavy vehicle activity in Ventersburg, where an urban speed restriction is in place.
Duration of Work	Reseal until April 2012. Ventersburg realignment until September 2014.
Contact for Routine Road Maintenance	Japie Taljaard 082 857 7175

National Route	N1
Section	Kroonstad to Vaal River (Free State – Gauteng Provincial Boundary)
Distance	102 km
Description	Partly a single carriageway with alternating passing lanes in each direction and wide gravel shoulders, and partly a four-lane single carriageway, except for the 10 km portion beyond the Vaal Toll Plaza, where it becomes a four-lane dual carriageway with wide paved shoulders.
Condition of Road	Good.
Comments	
Duration of Work	
Contact for Routine Road Maintenance	Japie Taljaard 082 857 7175

National Route	N1
Section	Vaal River (provincial boundary) to Johannesburg
Distance	64 km
Description	Four-lane dual carriageway freeway with wide paved shoulders.
Condition of Road	Good.
Comments	Motorists should beware of pedestrian activity along the route. Additional street lighting has been installed at the Ennerdale Interchange.
Duration of Work	
Contact for Routine Road Maintenance	Herman du Plessis 082 721 4886

National Route	N1
Section	Johannesburg to Pretoria (N4 Interchange)
Distance	84 km
Description	Four-lane dual carriageway freeway from Soweto to Roodepoort changing into six-lane dual carriageway freeway from Roodepoort to Pretoria.
Condition of Road	Good.
Comments	Construction of additional lanes and other improvements. Lane restrictions in off peak periods.
Duration of Work	Completion November 2011
Contact for Routine Road Maintenance	Henk Diedericks 082 704 6553

For up to date traffic information on construction works on the Gauteng Freeway Improvement Project, please visit www.i-traffic.co.za.

National Route	N1 (GFIP)
Section	Misgund (Soweto) to Buccleuch
Distance	38 km
Description	Construction of six lanes and upgrade of Interchanges – Lane restriction in off peak hours
Comments	Expected completion November 2011
Duration of Work	30 months

National Route	N1 Section 20 & 21 (GFIP)
Section	Buccleuch to Brakfontein Interchange
Distance	23 km
Description	Construction of six lanes and upgrade of Interchanges – Lane closures at night.
Comments	March 2012
Duration of Work	

National Route	N1
Section	Section 20 & 14 th Avenue to Buccleuch
Distance	
Description	Construction of lanes & upgrade of Interchanges
Condition of the road	
Comments	Lane closures at night
Duration of work	March 2012
Contact for Routine Road Maintenance	Hennie Kotze 083 283 6051

National Route	M1
Section	Buccleuch to Corlett Drive
Distance	
Description	Construction of lanes & upgrade of Interchanges
Condition of the road	
Comments	Lane closure off peak hours
Duration of work	May 2012
Contact for Routine Road Maintenance	Hennie Kotze 083 283 6051

National Route	N1 (GFIP)
Section	Brakfontein to N4 Interchange
Distance	10 km
Description	Construction of six lanes and upgrade of Interchanges – Lane restriction in off peak hours
Comments	Expected completion November 2011
Duration of Work	30 months

National Route	N1
Section	Pretoria (N4 Interchange) to Bela Bela (Warmbaths) (Platinum Toll highway)
Distance	94 km
Description	Six-lane dual carriageway freeway from Pretoria (Proefplaas Interchange) to Zambesi Interchange changing into four-lane dual carriageway freeway to Bela Bela.
Comments	No construction
Duration of Work	
Contact for Routine Road Maintenance	Pt Ops 012 804 0044

National Route	N1
Section	Bela Bela to Polokwane (Great North Toll Road)
Distance	160 km
Description	Four-lane dual carriageway freeway from the Warmbaths/Settlers interchange to the Kranskop toll plaza. Four-lane single carriageway freeway from the Kranskop Toll Plaza to the N1/R71 interchange at Polokwane.
Comments	No Construction
Duration of Work	
Contact for Routine Road Maintenance	NTRV Danie Kotze 082 822 0902

National Route	N1
Section	Polokwane (Pietersburg) to Louis Trichardt
Distance	98 km
Description	Two-lane single carriageway with paved shoulders.
Condition of Road	Very good.
Comments	Routine Road Maintenance teams may be encountered
Duration of Work	
Contact for Routine Road Maintenance	George Brand 082 555 8493

National Route	N1
Section	Louis Trichardt to Masekwaspoort
Distance	28 km
Description	Two-lane single carriageway with passing/climbing lanes and no paved shoulders.
Condition of Road	Good.
Comments	Patching work – Routine Road Maintenance Teams may be encountered.
Duration of Work	
Contact for Routine Road Maintenance	George Brand 082 555 8493

National Route	N1
Section	Musina to Beit Bridge
Distance	15 km
Description	Two-lane single carriageway with paved shoulders
Condition of Road	Good
Comments	Patching work – Routine Road Maintenance Teams may be encountered.
Duration of Work	
Contact for Routine Road Maintenance	George Brand 082 555 8493

National Route	N1
Section	Masekwaspoort to Musina
Distance	62 km
Description	Two-lane single carriageway with passing lanes, but paved shoulders only on last 20 Km before Musina.
Condition of Road	Good.
Comments	Patching work – Routine Road Maintenance Teams may be encountered.
Duration of Work	
Contact for Routine Road Maintenance	George Brand 082 555 8493

N2

National Route	N2
Section	Swartklip Interchange to Somerset-West
Distance	24 km
Description	Two-way dual carriageway with paved shoulders
Condition of Road	Good.
Comments	Routine road maintenance teams may be encountered
Duration of Work	Ongoing.
Contact for Routine Road Maintenance	Heuppschenne Lekay 082 782 9155

National Route	N2
Section	Somerset-West to Botriver
Distance	45 km
Description	Single carriageway road with narrow paved shoulders and climbing lanes are provided through Sir Lowry's Pass. A four (4)- lane single undivided carriageway road through Sir Lowry's Pass and Houwhoek Pass.
Condition of Road	Good.
Comments	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing.
Contact for Routine Road Maintenance	Heuppschenne Lekay 082 782 9155

National Route	N2
Section	Botriver to Caledon
Distance	30 km
Description	Single carriageway with paved shoulders and climbing lanes.
Condition of Road	Good.
Comments	Routine road maintenance teams may be encountered
Duration of Work	Ongoing.
Contact for Routine Road Maintenance	Pierre Terblanche 084 516 7121

National Route	N2
Section	Caledon to Riviersonderend
Distance	48 km
Description	Single carriageway with paved shoulders and climbing lanes.
Condition of Road	Good.
Comments	Routine road maintenance teams may be encountered
Duration of Work	Ongoing.
Contact for Routine Road Maintenance	Pierre Terblanche 084 516 7121

National Route	N2
Section	Riviersonderend to Swellendam
Distance	58 km
Description	Single carriageway with paved shoulders.
Condition of Road	Good.
Comments	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing.
Contact for Routine Road Maintenance	Pierre Terblanche 084 516 7121

National Route	N2
Section	Swellendam to Riversdale
Distance	82 km
Description	Single carriageway with paved shoulders.
Condition of Road	Good.
Comments	Construction works are in progress approximately 25 kilometres east of Riversdale over a 33 km section. Motorists can encounter up to three manually controlled Stop/Go sections during the day and traffic signal units at night with waiting periods on average 15 minutes.
Duration of Work	August 2011 until June 2012
Contact for Routine Road Maintenance	Pierre Terblanche 084 516 7121

National Route	N2
Section	Riversdale to Mossel Bay
Distance	82 km
Description	Single carriageway with paved shoulders.
Condition of Road	Good.
Comments	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing.
Contact for Routine Road Maintenance	John Strydom 083 677 9401

National Route	N2
Section	Mossel Bay to George
Distance	51 km
Description	A four-lane dual carriageway.
Condition of Road	Good.
Comments	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing.
Contact for Routine Road Maintenance	John Strydom 083 677 9401

National Route	N2
Section	George to Knysna
Distance	54 km
Description	Single carriageway with paved shoulders and climbing lanes.
Condition of Road	Good with the exception of Knysna Lagoon Bridge to Knysna Town. From the Knysna Lagoon Bridge to Knysna town the road is uneven and very narrow with no overtaking opportunities.
Comments	Routine road maintenance teams may be encountered. Motorists should be alert to pedestrians and/or stray animals in the vicinity of Knysna Lagoon. Motorists should also be alert to hawkers selling alongside the road. It is illegal to stop and buy from the sellers.
Duration of Work	Ongoing.
Contact for Routine Road Maintenance	John Strydom 083 677 9401

National Route	N2
Section	Knysna to Plettenberg Bay
Distance	39 km
Description	Single carriageway with narrow paved shoulders.
Condition of Road	Good.
Comments	Construction works are in progress between Knysna and Harkerville. Motorists can encounter up to two manually controlled Stop/Go sections during the day with waiting periods on average 20 minutes. Motorists should be alert to pedestrians and/or stray animals in the vicinity of the informal settlement in Knysna, as well as in the vicinity of Plettenberg Bay.
Duration of Work	June 2011 until April 2012
Contact for Routine Road Maintenance	John Strydom 083 677 9401

National Route	N2
Section	Plettenberg Bay to Natures Valley T-Junction (Sout River)
Distance	20 km
Description	Single carriageway with narrow paved shoulders and climbing lanes.
Condition of Road	Good.
Comments	Motorists should be alert to pedestrians and/or stray animals in the vicinity of the Craggs.
Duration of Work	
Contact for Routine Maintenance	John Strydom 083 677 9401

National Route	N2
Section	Natures Valley to Storms River
Distance	40 km
Description	A two-lane single carriageway with surfaced shoulders.
Condition of Road	Good
Comments	Toll Road
Contact for Routine Road Maintenance	Jaco Klopper 083 446 8501

National Route	N2
Section	Storms River Town to Elands River
Distance	14 km
Description	A two-lane single carriageway with shoulders.
Condition of Road	Good
Comments	Toll Road
Contact for Routine Road Maintenance	Jaco Klopper 083 446 8501

National Route	N2
Section	Elands River to Gamtoos
Distance	98 km
Description	A two-lane single carriageway with shoulders.
Condition of Road	Good
Comments	Construction work in Progress with lane closures. Some sections of road are without line markings. STOP/GO conditions with 60km/h restrictions
Duration of work	June 2011
Contact for Construction	Loest Smit 082 587 9040

National Route	N2
Section	Gamtoos River to Van Stadens River
Distance	19 km
Description	14,7 km of 2-lane single carriageway and 4.3 km of dual carriageway with surfaced shoulders.
Condition of Road	Good
Comments	
Duration of Work	
Contact for Routine Road Maintenance	Jaco Klopper 083 446 8501

National Route	N2
Section	Van Stadens River to Port Elizabeth (Markman)
Distance	57 km
Description	A 4-lane dual carriageway freeway.
Condition of Road	Good
Comments	Section between St Albans and Bramlin has no edge lines and construction has commenced in Nov. 2011. Impact on road users will be minimal up to Jan 2011. Reduced speeds, will however, apply.
Duration of Work	
Contact for Construction	Harry Wilson 072 306 1612
Contact for Routine Road Maintenance	Jaco Klopper 083 446 8501

National Route	N2
Section	Port Elizabeth (Coega IDZ) to Colchester
Distance	50Km
Description	40 km freeway and 10km 2 lane under construction.
Condition of Road	Fair, but narrow and uneven in places and prone.
Comments	Between Coega and Colchester construction works are in progress with limited impact on road users. Caution should be exercised at construction vehicle entry and exiting positions. 60 kph restrictions are in place for working hours
Duration of Work	Until March 2013
Contact for construction project	Jan Verduyn 082451 0346
Contact for Routine Road Maintenance	Siyam Rune 082 309 2311

National Route	N2
Section	Fish river to Keiskamma Pass
Distance	27 km
Description	A 2-lane single carriageway
Condition of Road	Under construction
Comments	Road under construction with reduced speed restriction of 60-80km/h to be aware of turning trucks
Duration of Work	Until March 2013
Contact for Routine Road Maintenance	Siyam Rune 082 309 2311
Contact for Construction project	Harold Webster 083 452 6343

National Route	N2
Section	Keiskamma River to Green River
Distance	23 km
Description	A 2-lane single carriageway under construction.
Condition of Road	Under construction.
Comments	Speed reduction of 60 and 80km/h will be encountered with Stop/Go. Please look out for turning trucks. Road users are requested to exercise caution where construction workers are encountered next to the roadway
Duration of Work	Until March 2013
Contact for Routine Road Maintenance	Siyam Rune 082 309 2311
Contact for Construction	Joe Coetzee 072 883 1183

National Route	N2
Section	King Williams Town to East London (Gonubie)
Distance	60 km
Description	A 4-lane dual carriageway
Condition of Road	Fair
Comments	Short-term road narrowing for repairs could be encountered, especially between King Williams Town and East London.
Duration of Work	
Contact for Routine Road Maintenance	Siyam Rune 082 309 2311

National Route	N2
Section	King Williams Town to East London (Gonubie)
Distance	60 km
Description	A 4-lane dual carriageway
Condition of Road	Fair
Comments	Short-term road narrowing for repairs could be encountered, especially between King Williams Town and East London.
Duration of Work	
Contact for Routine Road Maintenance	Siyam Rune 082 309 2311

National Route	N2
Section	East London (Gonubie) to Kei River
Distance	60 km
Description	The first 2km is a 4-lane dual carriageway. Thereafter it becomes a 2-lane single carriageway with wide paved shoulders. Climbing lanes are provided on some steep grades.
Condition of Road	The condition is fair to good, except for the section between Gonubie out Brakfontein interchanges where the riding quality is uneven. Construction from Nov 2011 on this section. With reduce speed restrictions up to 60km/h effective from Jan 2012.
Contact for Construction	Nick Kitsopoulns 082 576 4667
Contact for Routine Road Maintenance	Mike Coetzee 082 321 7946

National Route	N2
Section	Kei River to Dutywa
Distance	68 km
Description	Single carriageway road with paved shoulders and climbing lanes.
Condition of Road	The condition is good.
Comments	
Duration of work	
Contact for Routine Road Maintenance	Mike Coetzee 082 321 7946

National Route	N2
Section	Dutywa to Mthatha
Distance	85 km
Description	Single carriageway road with paved shoulders and climbing lanes. Road surface failures / potholes may occur especially after heavy rains between the SitebeKomkhulu intersection and Mthatha, which is under construction and where lane reduction, closures and and speed reduction will be encountered.
Condition of Road	Fair
Duration of work	April 2013
Contact for Routine Road Maintenance	Mike Coetzee 082 321 7946
Contact for Construction Project	Renier Speyers 0824409148.

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered.

National Route	N2
Section	Mthatha to Mount Ayliff
Distance	130 km
Description	A 2 lane single carriageway with climbing lanes and paved shoulders. (Up to Mt. Frere no passing lanes between Mt. Frere and Brooks Nek) except the last 16km.
Condition of Road	The condition of the road between km 54 to km 70 is fair however routine maintenance may be encountered.
Contact for Routine Road Maintenance	Trevor Morgan 082 331 9085

National Route	N2
Section	Mount Ayliff to Brookes Nek (Provincial Boundary)
Distance	40 km
Description	A 2 lane single carriageway with climbing lanes and paved shoulders. (Up to Mt. Frere no passing lanes between Mt. Frere and Brooks Nek) except the last 16km.
Condition of Road	The condition of the road between km 54 to km 70 is fair however routine maintenance may be encountered.
Comments	The rehabilitation of this section of the N2 has started. Speed reductions and Stop/Go's situations may be encountered
Duration	March 2014
Contact for Construction	Gerard Downing 083 262 7143
Contact for Routine Road Maintenance	Trevor Morgan 082 331 9085

National Route	N2
Section	Brookes Nek (provincial boundary) to Port Shepstone
Distance	135 km
Description	This first section of the N2 in KZN is a two-lane single carriageway with narrow paved shoulders. Climbing lanes are provided on all the severe grades with the exception of a short 6 km section 26 km north of Kokstad.
Condition of Road	Good.
Comments	Between Staffords Post and Izingolweni the road will be resealed commencing in January 2012 with isolated repair works occurring from August 2011. Stop/Go controls will be in place during this period except for the period between 15 December 2011 and 9 January 2012 when no work will be undertaken.. Motorists to be aware of pedestrian activity between Harding and Port Shepstone.
Duration of Work	August 2011 to May 2012
Contact for Routine Road Maintenance	Amit Bhoora 082 442 9646

National Route	N2
Section	Port Shepstone to Durban (N2/N3 Interchange)
Distance	114 km
Description	The first 20 km is a single carriageway road with three lanes of traffic and narrow paved shoulders allowing overtaking opportunities. Thereafter the road becomes a four-lane dual carriageway with wide paved shoulders. The last 17 km leading into Durban has 3 lanes in each direction and is heavily trafficked.
Condition of Road	Good.
Comments	A 23km section between Oribi Toll Plaza and Hibberdene Interchange will be repaired between September 2011 and July 2012. Lane restrictions will be in place under reduced speed limits and stop/go controls will be in place until 15 December 2011. A project for the replacement of block paving at the Oribi toll plaza is in progress and will continue until December 2011. A project for the rehabilitation of the N2 between Mkomazi River and Lovu River commenced in October 2011. Included within this section is the construction of the Bonnyrigg Interchange. Lane closures and reduced speeds will be enforced, with no Stop/Go controls envisaged. Pavement repairs between Hibberdene and Umdloti on selected sections starting November 2011. There will be lane closures and some of the work will be done at night.
Duration of Work	Up to July 2012 – Oribi Toll Plaza to Hibberdene Interchange Up to January 2013 – Mkomazi River to Lovu River
Contact for Routine Road Maintenance	Amit Bhoora 082 442 9646 (Port Shepstone to Hibberdene) Tony Mathebula 082 670 2849 / 24hr number 074 583 3576 (Hibberdene to Durban)

National Route	N2
Section	Durban to Empangeni
Distance	162 km
Description	For 71 km, up to Stanger, the road is a four-lane dual carriageway. For the next 52 km, up to the Mtunzini Toll Plaza, the road is a four-lane undivided carriageway with paved shoulders. The remaining portion is a single carriageway with alternating passing opportunities.
Condition of Road	Good.
Comments	1. Major improvements to Umgeni Road Interchange will result in disruptions to traffic on the N2 and cross roads. Speed restrictions will be signposted. 2. A contract for reconstruction of the Ballito Interchange is in progress. Speed restrictions are signposted. 3. Capacity improvements on N2 Section 26 commenced in November 2011. The project entails the addition of lanes over the project length (km 11.0) to Km 21.0). Lane closures and reduced speeds will be enforced.
Duration of Work	The contract period for Umgeni Road Interchange will be until September 2013. The contract period for the N2 Section 26 contract will be until June 2014. Ballito Interchange completion is September 2012.
Contact for Routine Road Maintenance	Tony Mathebula 082 670 2849 / 24hr number 074 583 3576 (Durban to Umdloti) Bill Morris 0836554228 (Umdloti to Empangeni)

National Route	N2
Section	Empangeni to Pongola
Distance	250 km
Description	A 2-lane single carriageway with paved shoulders.
Condition of Road	Good
Comments	The construction of KwaMbonambi Interchange on Section 29 (km 36.2) is in progress. Traffic will be diverted onto on and off ramps between January 2012 and May 2012. Speed restrictions are signposted as 60 km/hr.
Duration of work	Until April 2012
Contact for Routine Road Maintenance	Gonie Govender 084 466 2198

National Route	N2
Section	Pongola to KwaZulu-Natal / Mpumalanga Border
Distance	38 km
Description	A 2-lane single carriageway road with gravel shoulders
Condition of Road	Good
Comments	Minor works is currently being carried out on the road shoulders.
Duration of work	December 2011
Contact for Routine Road Maintenance	Gonie Govender 084 466 2198

National Route	N2
Section	Mpumalanga Border north of Pongola to Piet Retief
Distance	44 km
Description	A two-lane single carriageway with narrow gravel shoulders.
Condition of Road	Poor
Comments	Under Rehabilitation. Stop/Go controls will be encountered and long delays can be expected
Duration of Work	Completion June 2012. Use alternate route if possible
Contact for Routine Road Maintenance	Hannelie Kruger 082 380 5264

National Route	N2
Section	Piet Retief to Ermelo
Distance	117 km
Description	A two-lane single carriageway with narrow gravel shoulders. First 7 kilometres is 4 lane undivided
Condition of Road	Poor. Stop/Go controls will be encountered and long delays can be expected
Comments	Rehabilitation in progress, use alternate route if possible
Duration of Work	June 2012
Contact for Routine Road Maintenance	Hendre du Preez 083 235 0141

National Route	N2 Section 33
Section	Piet Retief to Kwazulu Natal / Mpumalanga Border
Distance	
Description	
Condition of the road	
Comments	Road work up until 15 December 2011 – No Stop/Go
Duration of work	Construction will resume January 2012
Contact for Routine Road Maintenance	

National Route	N2 Section 34
Section	Piet Retief to Camden
Distance	
Description	Seal work for the next month. Stop/Go will be encountered at seal work teams. Stop/Go at line markings will also be encountered.
Comments	
Duration of Work	
Contact for Routine Road Maintenance	

National Route	N2 Section 34
Section	Camden to Ermelo
Distance	
Description	Rehabilitation of Pavement Works. 2 Way traffic diverted with New Jersey Barriers. Stop/Go will be encountered at Bridge Widening Section – 10minutes delay
Comments	
Duration of Work	July 2011
Contact for Routine Road Maintenance	

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered.

N3

National Route	N3
Section	Durban to Cedara (Hilton)
Distance	85 km
Description	This entire section is a multi-laned dual carriageway. The first four km out of Durban carries heavy traffic with up to 5 lanes in each direction. The next 40 km, up to Cato Ridge, has 3 lanes in each direction with wide paved shoulders. The section between Cato Ridge and the end of the Pietermaritzburg Bypass (33 km) has a two-lane plus paved shoulder configuration, except on steep gradients to the east of Pietermaritzburg where climbing lanes are provided. The final 14 km to Howick incorporates the notorious, steeply graded Town Hill, which has 3 lanes with paved shoulders in each direction.
Condition of Road	Mostly good but extensive patching works can be expected between Cato Ridge and Pietermaritzburg with possible lane closures down to one lane. Misty conditions occur frequently.
Comments	Construction is in progress at the Westville Viaduct for a steel pedestrian walkway. There will be shoulder closures on the northbound carriageway. Construction of a pedestrian bridge south of the Mariannahill Toll Plaza is in progress with expected completion in February 2012. Motorists are urged to obey the speed restrictions. There will be shoulder closures and lane narrowing during the construction period. In Pietermaritzburg, the Chota Motala Interchange is being upgraded resulting in narrow lanes through the interchange construction area and restricted speed limits of 60km/hr. Congestion should be expected, particularly during morning and evening commuter peak hours. Pavement repairs between Durban and Hilton on selected sections will commence in November 2011. There will be lane closures and some of the work will be done at night.
Duration of Work	27 months (Chota Motala), 12 months (N3 mariannahill Pedestrian Bridge)
Contact for Routine Road Maintenance	Tony Mathebula 082 670 2849 / 24hr number 074 583 3576 Jared Reddy 082 478 1165

National Route	N3 (The N3 Toll Route operated by N3 Toll Concession(Pty)Ltd)
Section	Cedara to Heidelberg
Distance	415 km
Description	This section of road is a public private partnership between SANRAL and the N3Toll Concession (Pty) Ltd. This toll route is a four-lane dual carriageway road between Cedara and the Tugela Toll Plaza. From the Tugela Toll Plaza to the Wilge Toll Plaza(Villiers) the road is a four-lane single carriageway with shoulders of varying width. The section between the Tugela Toll Plaza and Warden has at-grade intersections and access roads. The remainder of the road between Villiers and Heidelberg is a four-lane dual carriageway with paved shoulders.
Condition of Road	Good.
Comments	Current planned construction works include: (i) Reseal between the Mngeni River (Howick) and Nottingham Road is in progress and the expected completion date is December 2011. (ii) Reseal between Escourt South Interchange and Frere Interchange is in progress and the expected completion date is March 2012. (iii) Reseal of Van Reenens Pass is in progress and the expected completion date is January 2012. (iv) Rehabilitation between Blackspruit and 42 nd Hill in the Harrismith vicinity is in progress and the expected completion date is January 2012. (v) Rehabilitation between Harrismith and Warden is in progress and the expected completion date is February 2012. (vi) Rehabilitation between Warden and Villiers is in progress and the expected completion date is December 2012. (vii) Ongoing routine road maintenance and litter collection. Through the construction zones, traffic may be restricted to one lane in each direction under reduced speed. During the period 15 December 2011 to 8 January 2012 all four lanes will be open to traffic. Road users are urged to obey speed limits, maintain safe following distances and to refrain from littering.
Duration of Work	Please see above. Maintenance personnel will be on standby to deal with any emergency repairs.
Contact for Routine Road Maintenance	N3TC Customer Care Line 0800 634 357 0800 N3 HELP

National Route	N3
Section	Heidelberg to Johannesburg
Distance	50 km
Description	Four-lane dual carriage freeway.
Condition of Road	Good.
Comments	Repairs to the road surface and resealing of the road are suspended till further notice. The construction of a new pedestrian bridge close to Spruit View has started.
Duration of Work	
Contact for Routine Road Maintenance	Henk Diedericks 082 704 6553

National Route	N3 (GFIP)
Section	Heidelberg Weg Interchange to Geldenhuis Interchange
Distance	12 km
Description	Construction of six lanes and upgrade of Interchanges – Lane restriction in off peak hours
Comments	Completion December 2011
Duration of Work	30 months

National Route	N3 (GFIP)
Section	Geldenhuis Interchange to Buccleuch Interchange
Distance	17,6 km
Description	Construction of six lanes and upgrade of Interchanges – Lane restriction in off peak hours
Comments	Completion December 2011
Duration of Work	30 months

N4

National Route	N4 (Platinum Highway)
Section	Botswana Border to Zeerust
Distance	60 km
Description	Two-lane single carriageway with paved shoulders.
Condition of Road	Good.
Comments	No construction.
Duration of Work	
Contact for Routine Road Maintenance	Pt Ops 012 804 0044

National Route	N4 (Platinum Toll Highway)
Section	Zeerust to Rustenburg
Distance	120 km
Description	Two-lane single carriageway with paved shoulders.
Condition of Road	Good.
Comments	No Construction.
Duration of Work	
Contact for Routine Road Maintenance	Pt Ops 012 804 0044

National Route	N4 (Platinum Toll Highway)
Section	Rustenburg to Brits (R512 Interchange)
Distance	70 km
Description	Two-lane single carriageway freeway.
Condition of Road	Good.
Comments	Motorists must be aware and be on the look out for pedestrians and animals in the Bapong area. Adhere to posted speed limits.
Duration of Work	
Contact for Routine Road Maintenance	Pt Ops 012 804 0044

National Route	N4 West Magalies Toll Road
Section	Rebecca Street to Pelindaba
Distance	21 km
Description	Mixture of two-lane dual carriageway and two-lane single carriageway freeway.
Condition of Road	Good.
Comments	No construction.
Duration of Work	
Contact for Routine Road Maintenance	Herman du Plessis 082 771 4886

National Route	N4
Section	Pretoria to Hans Strydom Interchange
Distance	13.6 km
Description	A 6-lane dual carriageway road up to Simon Vermooten Interchange, thereafter a 4-lane dual carriage way.
Condition of Road	Good.
Comments	No construction.
Duration of Work	
Contact for Routine Road Maintenance	Philip Fourie 083 410 2601

National Route	N4
Section	Hans Strydom Interchange to Mozambique
Distance	304 km
Description	Four-lane dual carriageway from Hans Strydom Int. to Van Dyk's Drift. Thereafter, a four-lane undivided road to Wonderfontein, then 2 lanes undivided to the Mozambique border.
Condition of Road	Good.
Comments	No construction
Duration of Work	
Contact for Routine Road Maintenance	Trans African Concessionaires (TRAC) 013 755 3316

N5

National Route	N5
Section	Harrismith to Bethlehem
Distance	88 km
Description	A two-lane single carriageway with wide paved shoulders. There are overtaking opportunities where severe grades occur.
Condition of Road	Fair to good.
Comments	No construction activity between Harrismith and Kestell, but the wet season results in localised maintenance activity. A contract for the rehabilitation of the section between Kestell and Bethlehem is in progress and three sections with Stop/Go controls (and traffic lights at night) will be in operation at any one time. Expected completion date is December 2012.
Duration of Work	Maintenance work ongoing. Until December 2012 for Kestell to Bethlehem
Contact for Routine Road Maintenance	Hennie Grobbelaar 082 334 6197

National Route	N5
Section	Bethlehem to Winburg
Distance	120 km
Description	A two-lane single carriageway with varying width of either paved or gravel shoulders. There are overtaking opportunities where severe grades occur.
Condition of Road	Fair to good
Comments	Construction of a climbing lane at Paul Roux is in progress, with expected completion in February 2012. Maintenance crews will be active with occasional localised Stop/Go controls for asphalt patching work, between Bethlehem and Winburg
Duration of Work	Maintenance crews are continuously active. Climbing Lane construction until February 2012
Contact for Routine Road Maintenance	Hennie Grobbelaar 082 334 6197

N6

National Route	N6
Section	East London to Stutterheim
Distance	70 km
Description	A two-lane single carriageway with paved shoulders and climbing lanes in places
Condition of Road	Fair to good
Contact for Routine Road Maintenance	Flip Jacobs 082 563 5218
Comments	Reseal contract from East London to St. Luke Km 24 and Kei Road km 51 to Sutterheim to start during November 2011 and to be completed by end of March 2012
Contact for Construction	Ricardo Ceaser 078 934 6680

National Route	N6
Section	Stutterheim to Cathcart
Distance	49 km
Description	A two-lane single carriageway with paved shoulders and climbing lanes in places
Condition of Road	Good.
Contact for Routine Road Maintenance	Flip Jacobs 082 563 5218

National Route	N6
Section	Cathcart to Queenstown
Distance	59 km
Description	A two-lane single carriageway with paved shoulders and climbing lanes in places.
Condition of Road	Fair to Good
Contact for Routine Road Maintenance	Flip Jacobs 082 563 5218

National Route	N6
Section	Ezibeleni to JJ Serfontein inside Queenstown
Distance	6.5 Km
Description	Two-lanes single carriageway road. Dual carriageway through Queenstown, of which one carriageway is periodically closed for construction
Condition of Road	Fair to Poor
Comments	Construction has commenced at Queenstown, which will result in delays to road users.
Duration of Work	Till Dec 2012.
Contact for Routine Road Maintenance	Flip Jacobs 082 563 5218
Contact for Construction Project	Leon Harmse 082 300 1999

National Route	N6
Section	Queenstown to Aliwal North
Distance	58 km
Description	A two-lane single carriageway with paved shoulders.
Condition of Road	Fair to Good
Contact for Routine Road Maintenance	Flip Jacobs 082 563 5218

National Route	N6
Section	Aliwal North to Bloemfontein
Distance	200 km
Description	Predominantly, a two- lane single carriageway with only the last 2.36km National Route 6 and National Route 1 with wide paved shoulders. The rest of the route has gravel shoulders of varying widths.
Condition of Road	Only a 42km section between Reddersburg and Bloemfontein is in excellent condition. Between Aliwal North and Smithfield the road is in a good condition. The rest of the route is satisfactory – except for the section between Smithfield and Reddersburg which is currently being rehabilitated.
Comments	A contract for the rehabilitation of the 34km long section between Smithfield and Parys Hoogte (including the road through Smithfield) is in progress, with completion expected in December 2012. Two Stop/Go controls are in place during the day and at night and there is one deviation through Smithfield which is signposted. Construction works for the rehabilitation of the N6 from Parys Hoogte to Reddersburg will be completed in March 2012. There are three Stop/Go controls in place during the day and at night. These closures may cause delays of approximately 20 minutes each.
Duration of Work	March 2012 (Parys Hoogte to Reddersburg). December 2012 (Smithfield to Paryshoogte)
Contact for Routine Road Maintenance	Potgieter CJ (Pottie) 0825667301

N7

National Route	N7
Section	Melkbos Turn-off to Clanwilliam
Distance	198 km
Description	A single carriageway road with paved shoulders between Melkbos and Piekenierskloof Pass; thereafter gravel shoulders.
Condition of Road	Fair to Good.
Comments	Construction works are in progress between Piketberg and Piekenierskloof Pass. Motorists can encounter up to four manually controlled Stop/Go sections during the day with waiting periods on average 15 minutes. Construction works are also in progress on the Piekenierskloof Pass between the Eendekuil and Citrusdal turn offs. Motorists will experience two manually controlled Stop/Go sections during the day and traffic signal units at night with waiting periods on average 20 minutes. Motorists should also be aware that the gravel shoulders between Piekenierskloof Pass and Clanwilliam are very narrow.
Duration of Work	July 2010 until June 2012
Contact for Routine Road Maintenance	Sandla Tsengiwe 083 701 4979

National Route	N7
Section	Clanwilliam to Northern Cape Border
Distance	188 km
Description	A single carriageway road with gravel shoulders.
Condition of Road	Fair to Good.
Comments	Motorists may encounter occasional short-term closures over short sections for routine maintenance.
Duration of Work	Ongoing.
Contact for Routine Road Maintenance	Louis Burger 074 193 2978

National Route	N7
Section	Northern Cape Border to Vioolsdrift
Distance	412 km
Description	A single carriageway road with gravel shoulders.
Condition of Road	Good.
Comments	Routine road maintenance teams may be encountered. Motorists should also be alert to pedestrians and/or stray animals in the vicinity of Okiep and Steinkopf.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Chris Roux 083 440 7553

N8

National Route	N8
Section	Groblershoop to Kimberley
Distance	285 km
Description	Single carriageway with paved shoulders. Stopping places are provided at regular intervals.
Condition of Road	Fair.
Comments	Construction works are in progress between Kimberley and Campbell. Motorists can encounter up to four manually controlled Stop/Go sections during the day and one traffic signal units at night with waiting periods on average 10 minutes. Motorists should also be alert to stray animals along the route.
Duration of Work	March 2011 until December 2012
Contact for Routine Road Maintenance	Ofan Mothakane 079 879 4720

National Route	N8
Section	Kimberley to Bloemfontein
Distance	150 km
Description	Predominantly, a two-lane single carriageway. The 29 km section between Kimberly and Perdeberg has paved shoulders, while the final eight km immediately adjacent to Bloemfontein is four – lane dual carriageway with wide paved shoulders. The remainder of the road has gravel shoulders.
Condition of Road	Fair
Comments	<ol style="list-style-type: none"> 1. Resealing of the section between Kimberley and Alexanderfontein (30 kms) will commence in January 2012 with stop/go restrictions during the day. No restrictions at night. 2. Rehabilitation work on the section between Alexanderfontein and Petrusburg (49.5 kms) commenced in October 2011. No stop/go controls currently in place. 3. Maintenance works are continuous Petrusburg and Bloemfontein. Be aware of potholes developing in this area with temporary pothole signs warning the motorists. 4. Rehabilitation work on the section between De Brug and Kloofeind (31.5 kms) commenced in April 2011. Up to three stop/go sections under signalised controls (day and night) can be expected with up to 20 minute delays at each.
Duration of Work	Kimberley – Alexanderfontein until June 2012. Alexanderfontein – Petrusburg until August 2013. De Brug – Kloofeind until April 2013.
Contact for Routine Road Maintenance	Potgieter CJ (Pottie) 0825667301

National Route	N8
Section	Bloemfontein to Maseru
Distance	135 Km
Description	The first five km from Bloemfontein is four-lane dual carriageway with wide paved shoulders. Between Bloemfontein and Thaba Nchu there are alternating passing and climbing lanes. Between Thaba Nchu and Ladybrand is a two-lane single carriageway road with shoulders of varying widths.
Condition of Road	Good – Except for the section between Tweespruit and Ladybrand which is being rehabilitated.
Comments	Construction of the Thaba Nchu Interchange is in progress with speed and height restrictions. Motorists are urged to obey the posted speed limits. Rehabilitation work on the section between Tweespruit and Ladybrand is in progress and traffic is accommodated by means of three Stop/Go controls where delays of up to 20 minutes at each can be expected.
Duration of Work	N8 Tweespruit to Ladybrand up to July 2013. Completion date for Thaba Nchu Interchange is October 2012.
Contact for Routine Road Maintenance	Potgieter CJ (Pottie) 0825667301

N9

National Route	N9
Section	Western Cape and Eastern Cape Boundary to Aberdeen
Distance	138 km
Description	A two-lane single carriageway with gravel shoulders.
Condition of Road	Good
Comments	No construction but motorists may encounter occasional short-term closures over short sections for routine maintenance.
Contact for Routine Road Maintenance	Johan Dorfling 082 847 6615

National Route	N9
Section	Aberdeen to Graaff Reinet
Distance	54 km
Description	A two-lane single carriageway with paved shoulders.
Condition of Road	Good.
Comments	No construction but motorists may encounter occasional short-term closures over short sections for routine maintenance.
Duration of Work	
Contact for Routine Road Maintenance	Johan Dorfling 082 847 6615

National Route	N9
Section	Graaff-Reinet to Middelburg
Distance	105 km
Description	A Two-Lane single carriageway with paved shoulders
Condition of Road	Good.
Contact for Routine Road Maintenance	Johan Dorfling 082 847 6615

National Route	N9
Section	Middelburg to the intersection of the N10 and N9 between Middelburg and Noupoort (Carlton Heights)
Distance	24 km
Description	Single carriageway with short section of paved shoulders.
Condition of Road	Fair to Poor
Comments	No construction but motorists may encounter occasional short-term closures over short sections for routine maintenance.
Contact for Routine Road Maintenance	Johan Dorfling 082 847 6615

National Route	N9
Section	Colesberg to Carlton Heights
Distance	70 km
Description	Single carriageway with gravel shoulders.
Condition of Road	Fair
Comments	Construction works are in progress between Colesberg and Noupoort. Motorists can encounter up to four manually controlled Stop/Go sections during the day and traffic signal units at night with waiting periods on average 15 minutes.
Duration of Work	April 2010 to June 2012
Contact for Routine Road Maintenance	Dewet Lodewyk 083 383 8174

N10

National Route	N10
Section	Paterson – Olifantskop Pass
Distance	23 km
Description	Two lane single carriageway road. Some passing lanes in pass
Condition of Road	
Duration of work	December 2011
Comments	Repair work from Paterson to Olifantskop Pass commenced in 2010. The project entails the addition of passing lanes, localized repairs and resealing of the road. Traffic will be accommodated by means of stop-go control during daylight hours with delays on the pass section.
Contact for Routine Road Maintenance	Marko du Plessis 079 893 6256
Contact for construction	Rudi Botha 083 275 0052

National Route	N10
Section	Olifanskop Pass to Middleton
Distance	134 km
Description	This section is a two-lane single carriageway road with wide surfaces shoulders.
Condition of Road	
Comments	The construction of the Repair and Reseal Project between Olifantskop Pass and Jaskraal (Middleton) commenced in December 2010. The length of the project is approximately 46 km. The project entails localised repairs and resealing of the road. Seal work has ceased over winter and has commence again in August 2011.
Contact for Routine Road Maintenance	Marko du Plessis 079 893 6256
Contact for Construction	Rodney Spies 083 633 6558
Duration of Work	Feb 2012

National Route	N10
Section	Baviaans River to Cradock
Distance	62 km
Description	The first 10 km is a two-lane single carriageway road with narrow gravel shoulders and climbing lanes on some severe grades. Thereafter it becomes a two-lane single carriageway with narrow paved shoulders.
Condition of Road	Fair/Poor.
Comments	Construction works are in progress on this section of road at Cradock. Motorists will encounter delays of up to 30 minutes at STOP/GO controls. Within Cradock delays will be encountered where half of streets will be closed.
Duration of work	Up to March 2012
Contact for Routine Road Maintenance	Marko du Plessis 079 893 6256
Contact for Construction	Teuns Lewis 084 643 1832

National Route	N10
Section	Cradock to Middelburg
Distance	95 km
Description	The first 43 km is a two-lane single carriageway road with wide paved shoulders. The last 30 km is a two-lane single carriageway road with narrow gravel shoulders. .
Condition of Road	Fair
Comments	The construction of the upgrading project between Tafelberg and Middleburg commenced in May 2011. The length of the project is approximately 24 km. The entails upgrading and widening of the road, as well as upgrading and realignment of the Middleburg intersection. Traffic will be accommodated by means of temporary deviations, as well as STOP/GO control during daylight hours and traffic light control at night.
Duration of Work	Up to April 2013
Contact for Routine Road Maintenance	Marko du Plessis 079 893 6256
Contact for construction project	Johan Knoesen 082 417 4778

National Route	N10
Section	Ludlow (Intersection of the N10 and N9 between Middelburg and Noupoort) to Hanover
Distance	62 km
Description	Single carriageway with short section of paved shoulders and thereafter gravel shoulders.
Condition of Road	Fair
Comments	Construction works are in progress between Ludlow and Hanover. Motorists can encounter up to three manually and traffic-light controlled Stop/Go sections with waiting period on average 10 minutes.
Duration of Work	September 2010 until December 2011.
Contact for Routine Road Maintenance	Roland Siebrits 073 424 9767

National Route	N10
Section	Hanover to De Aar
Distance	64 km
Description	Single carriageway with narrow paved shoulders.
Condition of Road	Fair to Good
Comments	Construction works are in progress between Hanover and De Aar. Motorists can encounter up to four manually and traffic-light controlled Stop/Go sections with waiting period on average 10 minutes.
Duration of work	February 2011 until March 2012.
Contact for Routine Road Maintenance	Roland Siebrits 073 424 9767

National Route	N10
Section	De Aar to Britstown
Distance	48 km
Description	Single carriageway with short section of paved shoulders; thereafter gravel shoulders.
Condition of Road	Good
Comments	Construction work is in progress at the Brak River bridge between De Aar and Britstown. Motorists can encounter a Stop/Go section during the day and traffic signal units at night with waiting period on average 10 minutes. Abnormal vehicles should note that a width restriction of 3.2m and a maximum load capacity of 45 tons are applicable over the Brak River bridge.
Duration of Work	May 2011 until December 2011
Contact for Routine Road Maintenance	Roland Siebrits 073 424 9767

National Route	N10
Section	Britstown to Prieska
Distance	126 km
Description	Single carriageway with gravel shoulders.
Condition of Road	Good
Comments	Construction works are in progress between Britstown and Prieska. Motorists can encounter up to four manually and traffic-light controlled Stop/Go sections with waiting period on average 10 minutes.
Duration of Work	July 2011 until June 2012
Contact for Routine Road Maintenance	Roland Siebrits 073 424 9767

National Route	N10
Section	Prieska to Groblershoop
Distance	129 km
Description	Single carriageway with gravel shoulders.
Condition of Road	Good
Comments	Construction works are in progress between Prieska and Groblershoop. Motorists can encounter up to eight manually and traffic-light controlled Stop/Go sections with waiting period on average 10 minutes.
Duration of Work	July 2011 until June 2012
Contact for Routine Road Maintenance	Charles van Wyk 076 281 1433

National Route	N10
Section	Groblershoop to Upington
Distance	116 km
Description	Single carriageway with gravel shoulders. Road widening through winelands of Orange River Valley with sharp curves and steep gradients.
Condition of Road	Fair to good.
Comments	Routine road maintenance teams may be encountered. Motorists should also be alert to pedestrians and/ or stray animals in the road reserve.
Duration of Work	Ongoing.
Contact for Routine Road Maintenance	Charles van Wyk 076 281 1433

National Route	N10
Section	Upington to Nakop (Namibian Border)
Distance	134 km
Description	Single carriageway road with gravel shoulders.
Condition of Road	Good.
Comments	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing.
Contact for Routie Road Maintenance	Charles van Wyk 076-281-1433

N11

National Route	N11
Section	N3 Bergville Interchange to Newcastle
Distance	115 km
Description	A two-lane single carriageway with narrow shoulders, except for the 16 km portion before Newcastle and for short sections through the Biggarsberg Mountain range, where there are passing lanes.
Condition of Road	Variable, generally good.
Comments	<ol style="list-style-type: none"> 1. A rehabilitation project from the Bergville Interchange into Ladysmith (approximately 14km) is in progress. Three Stop/Go controls are in place during the day and at night over these sections of the N11 as well as a section of the R103 up to the Interchange of the N11/R103 where delays of up to 20 minutes at each can be expected. 2. Rehabilitation work on the section between Nkunzi River and the MR68 intersection to Dundee is in progress with two Stop/Go control measures in place during the day with traffic signal units at night, with delays of up to 20 minutes at each expected.
Duration of Work	Maintenance work ongoing. Rehabilitation from Bergville to Ladysmith up to August 2012. Nkunzi River to MR68 until March 2013.
Contact for Routine Road Maintenance	Ronald Dookhie 073 155 4944

National Route	N11
Section	Newcastle to Volksrust
Distance	54 km
Description	Apart from the 9 km that constitute the Newcastle Bypass and the 17 km that make up the Laingsnek (Majuba) Mountain Pass, the road is a single carriageway, with narrow paved shoulders.
Condition of Road	Fair to good
Comments	The rehabilitation of the section from Newcastle to Ingogo Station is in progress. Anticipated completion date is February 2012. One Stop/Go control measure can be anticipated to be in place during the day and at night. Motorists can expect delays of up to 20 minutes.
Duration of Work	Newcastle to Ingogo: Until February 2012.
Contact for Routine Road Maintenance	Ronald Dookhie 073 155 4944

National Route	N11
Section	Volksrust to Amersfoort
Distance	50 km
Description	A two-lane single carriageway with narrow gravel shoulders. The whole section is heavily trafficked.
Condition of Road	Good
Comments	No Construction
Duration of Work	
Contact for Routine Road Maintenance	Timothy Maselesa 082 807 1089

National Route	N11
Section	Amersfoort to Ermelo
Distance	51 km
Description	A two-lane single carriageway road with narrow gravel shoulders.
Condition of Road	Poor.
Comments	Construction and road rehabilitation works in progress with Stop/Go at up to 2 work sections with possible delays of 20 minutes each. Road closures due to blasting operations will happen on some Sundays with a maximum delay of 2 hours.
Duration of Work	December 2011
Contact for Routine Road Maintenance	Timothy Maselesa 082 807 1089

National Route	N11
Section	Ermelo to Middelburg
Distance	101 km
Description	A two-lane single carriageway with wide gravel shoulders.
Condition of Road	Good. Erosion in places on gravel shoulders
Comments	No construction.
Duration of Work	
Contact for Routine Road Maintenance	Timothy Maselesa 082 807 1089

National Route	N11
Section	Middelburg to Groblersdal
Distance	82 km
Description	A two-lane single carriageway with narrow gravel shoulders.
Condition of Road	Good
Comments	No Construction
Duration of Work	
Contact for Routine Road Maintenance	Philip Fourie 083 410 2601

National Route	N11
Section	Groblersdal via Marblehall to Old Mpumalanga / Limpopo Border
Distance	38 km
Description	A two-lane single carriageway road with narrow gravel shoulders.
Condition of Road	Good
Comments	No Construction
Duration of Work	
Contact for Routine Road Maintenance	Philip Fourie 083 410 2601

National Route	N11
Section	Old Mpumalanga Border (North of Marble Hall) – Mokopane (Potgietersrust) – Groblersdrift Border Post
Distance	276 km
Description	Two-lane single carriageway.
Condition of the road	Good
Comments	No Construction
Duration of work	
Contact for Routine Road Maintenance	Stephan du Plessis

National Route	N11
Section	Roedtan to Mokopane
Distance	
Description	
Condition of the road	
Comments	Reseal work
Duration of work	May 2012
Contact for Routine Road Maintenance	Jonathan Geldenhuis 072 886 1526

N12

National Route	N12
Section	Three Sisters to Victoria-West
Distance	61 km
Description	Single carriageway with paved shoulders.
Condition of Road	Good.
Comments	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Johan Nel 082-612-1980

National Route	N12
Section	Victoria-West to Britstown
Distance	104 km
Description	Single carriageway with paved shoulders.
Condition of Road	Good.
Comments	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing.
Contact for Routine Road Maintenance	Johan Nel 082-612-1980

National Route	N12
Section	Britstown to Hopetown
Distance	134 km
Description	Single carriageway with narrow paved shoulders.
Condition of Road	Good.
Comments	Construction works are in progress between Britstown and Strydenburg. Motorists can encounter up to two traffic-light controlled Stop/Go sections with waiting period on average 10 minutes. Construction works are also in progress between Strydenburg and Hope Town. Motorists can encounter up to four traffic-light controlled Stop/Go sections with waiting period on average 15 minutes.
Duration of Work	June 2011 – August 2012.
Contact for Routine Road Maintenance	Johan Nel 082-612-1980

National Route	N12
Section	Hopetown to Kimberley
Distance	118 km
Description	Single carriageway with paved shoulders.
Condition of Road	Good.
Comments	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Milton van Heerden 083-362-9707

National Route	N12
Section	Kimberley to Northern Cape Border
Distance	85 km
Description	Single carriageway with paved shoulders.
Condition of Road	Good.
Comments	Routine Road Maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Milton van Heerden 083-362-9707

National Route	N12
Section	North West / Northern Cape Border at Warrenton to Christiana
Distance	42 km
Description	Two-lane single carriageway with unpaved shoulders.
Condition of Road	Fair to poor in places.
Comments	No construction.
Duration of Work	Completion May 2012
Contact for Routine Road Maintenance	George Brand 082 555 8493

National Route	N12
Section	Christiana to Bloemhof
Distance	52 km
Description	Two-lane narrow single carriageway with unpaved shoulders.
Condition of Road	Fair to poor and uneven in places.
Comments	The road is being reconstructed and widened on the section between Bloemhof and Beefmaster. 2 Stop/Go controls will be encountered between Wolmaranstad and Rietpan with delays of up to 20 minutes each. There will be reduced speed limits in place within these areas
Duration of Work	Completion May 2012
Contact for Routine Road Maintenance	George Brand 082 555 8493

National Route	N12
Section	Bloemhof to Wolmaranstad
Distance	64 km
Description	Two-lane narrow single carriageway with unpaved shoulders.
Condition of Road	Fair to poor and uneven in places.
Comments	The road is being reconstructed and widened on the section between Bloemhof and Beefmaster. 2 Stop/Go controls will be encountered between Wolmaranstad and Rietpan with delays of up to 20 minutes each. There will be reduced speed limits in place within these areas
Duration of Work	Completion May 2012
Contact for Routine Road Maintenance	George Brand 082 555 8493

National Route	N12
Section	Wolmaranstad to Klerksdorp
Distance	81 km
Description	Two-lane single carriageway with wide paved shoulders on most of the section, except closer to Klerksdorp.
Condition of Road	Good to very good.
Comments	No Construction
Duration of Work	
Contact for Routine Road Maintenance	George Brand 082 555 8493

National Route	N12
Section	Klerksdorp to Potchefstroom
Distance	25 km
Description	Two-lane narrow double carriageway with unpaved shoulders.
Condition of Road	Good.
Comments	No construction
Duration of Work	
Contact for Routine Road Maintenance	George Brand 082 555 8493

National Route	N12
Section	Potchefstroom to North West Border at Carltonville
Distance	51 km
Description	Two-lane narrow single carriageway with passing lanes.
Condition of Road	Fair.
Comments	No construction
Duration of Work	
Contact for Routine Road Maintenance	George Brand 082 555 8493

National Route	N12
Section	Diepkloof Interchange to Gauteng/Mpumalanga Border
Distance	50km
Description	Four-lane dual carriageway freeway.
Condition of Road	Fair to Good.
Comments	Reconstruction project between Gilloolys and R21 will start June 2008
Duration of Work	Expected completion April 2013
Contact for Routine Road Maintenance	Henk Diedericks 082 704 6553

National Route	N12 (GFIP)
Section	Reading to Elands Interchange
Distance	4 km
Description	Construction of six lanes and upgrade of Interchanges – Lane restriction in off peak hours
Comments	Expected completion December 2012
Duration of Work	30 months

National Route	N12
Section	Gauteng / Mpumalanga Border to Middelburg
Distance	115 km
Description	Four-lane dual carriageway freeway
Condition of Road	Fair to good. Rehabilitation finished 2008/2009
Comments	Reseal on the concrete section
Duration of Work	No construction
Contact for Routine Road Maintenance	Philip Fourie 083 410 2601

N14

National Route	N14
Section	Springbok to Pofadder
Distance	163 km
Description	Single carriageway with paved shoulders.
Condition of Road	Good.
Comments	Motorists should be alert to pedestrians and/or stray animals in Pofadder and ± 8 km west of Kuruman.
Duration of Work	
Contact for Routine Road Maintenance	Bernice Cloete 082-304 6553

National Route	N14
Section	Pofadder to Kakamas
Distance	130 km
Description	Single carriageway with paved shoulders.
Condition of Road	Good
Comments	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing.
Contact for Routine Road Maintenance	Bernice Cloete 082-304 6553

National Route	N14
Section	Kakamas to Keimoes
Distance	41km
Description	Single carriageway with gravel shoulders.
Condition of Road	Good.
Comments	Construction works are in progress between Kakamas and Keimoes. Motorists can encounter one manually controlled Stop/Go sections during the day and traffic signal units at night with waiting periods on average 10 minutes.
Duration of Work	July 2011 until June 2012
Contact for Routine Road Maintenance	Bernice Cloete 082-304 6553

National Route	N14
Section	Keimoes to Upington
Distance	35 km
Description	Single carriageway with paved shoulders.
Condition of Road	Good.
Comments	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing.
Contact for Routine Road Maintenance	Claudia Jannetjies 083-406-6371

National Route	N14
Section	Upington to Olifantshoek
Distance	166 km
Description	Single carriageway with short section of paved shoulders.
Condition of Road	Good.
Comments	Construction works are in progress approximately 70km west of Olifantshoek. Motorists can encounter up to two traffic control by means of Stop/Go measures during the day with waiting periods on average 10 minutes
Duration of Work	September 2010 until December 2011.
Contact for Routine Road Maintenance	Claudia Jannetjies 083-406-6371

National Route	N14
Section	Olifantshoek to Kuruman
Distance	97 km
Description	Single carriageway with gravel shoulders.
Condition of Road	Good.
Comments	Construction works are in progress between Olifantshoek and Kuruman. Motorists can encounter up to three manually controlled Stop/Go sections during the day with waiting periods on average 10 minutes.
Duration of Work	September 2010 until September 2012.
Contact for Routine Road Maintenance	Claudia Jannetjies 083-406-6371

National Route	N14
Section	Kuruman to Vryburg
Distance	132 km
Description	Single narrow carriageway with gravel shoulders.
Condition of Road	Good/Fair
Comments	No construction
Duration of Work	
Contact for Routine Road Maintenance	Nico Bosman 082 444 8858

National Route	N14 Section 8
Section	Kuruman to Vryburg
Distance	Km 0-142
Description	
Condition of the road	Good / Reseal work will be done by 15 December 2011
Comments	No construction
Duration of work	January 2012
Contact for Routine Road Maintenance	

National Route	N14
Section	Vryburg to Delareyville
Distance	82 km
Description	Single carriageway with gravel shoulders.
Condition of Road	Fair to poor.
Comments	Construction works in progress. Stop / Go controls may be encountered.
Duration of Work	December 2011
Contact for Routine Road Maintenance	Nico Bosman 082 444 8858

National Route	N14
Section	Delareyville to Coligny
Distance	104 km
Description	Single carriageway with gravel shoulders.
Condition of Road	Fair to poor.
Comments	Construction works in progress. Stop / Go controls may be encountered.
Duration of Work	December 2011
Contact for Routine Road Maintenance	Nico Bosman 082 444 8858

National Route	N14
Section	Coligny to Ventersdorp
Distance	53 km
Description	Single carriageway with gravel shoulders.
Condition of Road	Fair.
Comments	No construction
Duration of Work	
Contact for Routine Road Maintenance	Nico Bosman 082 444 8858

National Route	N14
Section	Sannieshof to Coligny
Distance	
Description	Road Markings – Depending on availability of material – Stop/Go will be encountered
Condition of Road	
Comments	
Duration of Work	
Contact for Routine Road Maintenance	

National Route	N14
Section	Ventersdorp to North West / Gauteng Border
Distance	101 km
Description	Single carriageway with gravel shoulders.
Condition of Road	Poor and uneven in places. Bypass in operation at sinkhole close to Gauteng provincial boundary
Comments	No construction
Duration of Work	
Contact for Routine Road Maintenance	Nico Bosman 082 444 8858

National Route	N14 Section 13
Section	Ventersdorp to North West / Gauteng Province Border
Distance	
Description	
Condition of the road	
Comments	Road work up until 15 December 2011 – No Stop/Go
Duration of work	Construction will resume January 2012
Contact for Routine Road Maintenance	

N17

National Route	N17
Section	Soweto to Nasrec
Distance	6 km
Description	New alignment
Condition of Road	Good
Comments	No Construction
Duration of Work	
Contact for Routine Road Maintenance	Marthinus Wilken 082 7821746

National Route	N17
Section	Johannesburg to Springs
Distance	35 km
Description	A 4-lane dual carriageway.
Condition of Road	Good.
Comments	No construction.
Duration of Work	
Contact for Routine Road Maintenance	Jack Mokwena 082 307 1697

National Route	N17
Section	Springs to Leandra
Distance	53 km
Description	Single carriageway with paved shoulders in places.
Condition of Road	Fair.
Comments	No Construction
Duration of Work	
Contact for Routine Road Maintenance	Philip Fourie 083 410 2601

National Route	N17
Section	Leandra to Leven Station
Distance	
Description	
Condition of the road	
Comments	Reseal in progress – 1 Stop/Go for 4km – 20 minute Delay
Duration of work	
Contact for Routine Road Maintenance	Johan Bruwer 082 788 2594

National Route	N17
Section	Leven Station to Trichardt
Distance	
Description	
Condition of the road	
Comments	Upgrade work in progress. All Stop/Go should be removed by 15 December 2011
Duration of work	

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered.

Contact for Routine Road Maintenance	Paul Wojtowitz 082 901 4831
--------------------------------------	--------------------------------

National Route	N17
Section	Trichardt to Bethal
Distance	
Description	
Condition of the road	
Comments	Upgrade Trichardt to Bethal completed. New bridge over Ogies road should be opened by 15 December 2011, allowing traffic to bypass town of Bethal. Rehabilitation of Moses Ketana should be complete by 15 December 2011
Duration of work	
Contact for Routine Road Maintenance	Johan Bruwer 082 788 2594

National Route	N17
Section	Davel to Ermelo
Distance	
Description	
Condition of the road	
Comments	Upgrade – At least two Stop/Go for 4km long & 20 minute delay at each.
Duration of work	Construction will resume January 2012
Contact for Routine Road Maintenance	Jan Gerber 082 551 1975

National Route	N17
Section	Bloemhof to Rietpan
Distance	
Description	
Condition of the road	
Comments	Upgrade – All Stop/Go will be removed by 15 December 2011
Duration of work	
Contact for Routine Road Maintenance	Tieker vd Berg 082 413 3479
National Route	N17
Section	Leandra to Kinross
Distance	15Km
Description	New Alignment
Condition of Road	N.A.
Comments	Completed
Duration of Work	December 2010
Contact for Routine Road Maintenance	H du Preez 083 235 0141

National Route	N17
Section	Kinross via Bethal to Ermelo
Distance	99 km
Description	Single carriageway with gravel shoulders.
Condition of Road	Fair to Poor, uneven in places.
Comments	There is rehabilitation between Trichardt & Bethal.
Duration of Work	Completed
Contact for Routine Road Maintenance	Timothy Maselesa 082 807 1089

National Route	N17
Section	Ermelo to Oshoek Border Post
Distance	122.59 km
Description	Single carriageway with paved shoulders.
Condition of Road	Fair, but uneven in places
Comments	No construction.
Duration of Work	
Contact for Routine Road Maintenance	Timothy Maselesa 082 807 1089

National Route	N17
Section	Rossetenville to Wits Rifle Road
Distance	
Description	
Condition of the road	
Comments	Overlay
Duration of work	April 2012
Contact for Routine Road Maintenance	Hendrik Amego 082 307 8106

N18 (R49)

National Route	N 18 (R49)
Section	Warrenton to Hartswater (Northern Cape Border)
Distance	55 km
Description	Single carriageway with paved shoulders.
Condition of Road	Good.
Comments	Motorists should be alert to pedestrians and / or stray animals.
Duration of Work	
Contact for Routine Road Maintenance	Milton van Heerden 083-362-9707

National Route	N 18
Section	Northern Cape / North West Border at Taung to Vryburg
Distance	119 km
Description	Single carriageway with gravel shoulders.
Condition of Road	Good.
Comments	No construction
Duration of Work	
Contact for Routine Road Maintenance	Sarel Oberholzer 083-417-7546

National Route	N18
Section	Northern Cape / North West Border to Mafikeng
Distance	
Description	2-3 Seal Teams will be encountered. Stop/Go will also be encountered with 10 minute delays Insitu Recycling on Asphalt Works
Comments	
Duration of Work	
Contact for Routine Road Maintenance	

National Route	N18
Section	Vryburg to Mafekeng
Distance	156 km
Description	Single carriageway with gravel shoulders.
Condition of Road	Good.
Comments	No construction
Duration of Work	
Contact for Routine Road Maintenance	Sarel Oberholzer 083-417-7546

OTHER NATIONAL ROUTES

National Route	R22
Section	Hluhluwe to Farazela (RSA/Mozambique border)
Distance	175 km
Description	A 2-lane single carriageway road with narrow paved shoulders throughout.
Condition of Road	Good
Comments	Speed humps have been installed at various locations and motorists are advised to observe the posted speed limits.
Duration of Work	
Contact for Routine Road Maintenance	Gonie Govender 084 466 2198

National Route	P720
Section	N2 to Golela Border Post with Swaziland
Distance	10 km
Description	A Single carriageway road between National Route 2 and Golela Border Post. Two lanes and a narrow paved shoulder and wide gravel shoulder in each direction.
Condition of Road	Fair to good.
Comments	No construction.
Duration of work	
Contact for Routine Road Maintenance	Gonie Govender 084 466 2198

National Route	R23
Section	Heidelberg to Standerton
Distance	93km
Description	Single carriageway road with paved shoulders.
Condition of Road	Variable but generally fair with rutting in some sections.
Comments	No construction.
Duration of Work	
Contact for Routine Road Maintenance	Johannes Dlomo 076 685 1388

National Route	R23
Section	Standerton to Volksrust
Distance	80 km
Description	Single carriageway road with unpaved shoulders.
Condition of Road	Fair to good. Fair with a lot of rutting.
Comments	No construction

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered.

Duration of Work	
Contact for Routine Road Maintenance	Johannes Dlomo 076 685 1388

National Route	R23
Section	Platrand
Distance	
Description	
Condition of Road	Fair
Comments	Stop/Go will be encountered
Duration of Work	January 2011
Contact for Routine Road Maintenance	

National Route	R21
Section	N1 to N12
Distance	30 km
Description	Dual carriageway.
Condition of Road	Fair to good
Comments	Additional lanes and upgrades to interchanges are taking place. Lane restrictions will be in place in off peak periods, expect delays
Duration of Work	December 2011
Contact for Routine Road Maintenance	Henk Diederiks 082 704 6553

National Route	R27
Section	Vanrhyns Pass to Calvinia
Distance	82 km
Description	Single carriageway road with gravel shoulders.
Condition of Road	Good.
Comments	Routine road maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Jacques Wentzel 079 514 3496

National Route	R27
Section	Calvinia to Brandvlei
Distance	147 km
Description	Single carriageway road with gravel shoulders.
Condition of Road	Good.
Comments	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing.
Contact for Routine Road Maintenance	Jacques Wentzel 079 514 3496

National Route	R27
Section	Brandvlei to Kenhardt
Distance	141 km
Description	Single carriageway road with gravel shoulders.
Condition of Road	Good.
Comments	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Johannes Rakwena 082 304 6880

National Route	R27
Section	Kenhardt to Keimoes
Distance	76 km
Description	Single carriageway road with gravel shoulders.
Condition of Road	Good.
Comments	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Johannes Rakwena 082 304 6880

National Route	S27
Section	Villiers to Heidelberg
Distance	62 km
Description	Single carriageway with gravel shoulders and short gravel road portion.
Condition of Road	Good (Gravel road in bad condition).
Comments	No construction.
Duration of Work	
Contact for Routine Road Maintenance	Johannes Dlomo 076 685 1388

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered.

National Route	R30/R730/R34 Toll Road
Section	Bloemfontein to Kroonstad via Brandfort/Welkom
Distance	210 km
Description	A single carriageway between National Route N1 and Virginia. It accommodates two lanes and has been upgraded with wide paved shoulders and ad hoc climbing lanes in each direction except for the 5km portion bypassing Brandfort which has four lanes and paved shoulders. The section between Virginia and Welkom is a double carriageway and the section between Welkom and Kroonstad is a four-lane undivided carriageway with paved shoulders.
Condition of Road	Good.
Comments	The upgrade between Glen Lyon Interchange and Brandfort North is expected to be completed by 9 December 2011. The upgrade between Brandfort North and Vet River is expected to be completed by the end of November 2011.
Duration of work	Until 9 December 2011
Contact for Routine Road Maintenance	Japie Taljaard 082 857 7175

National Route	R33
Section	From KwaZulu-Natal border, over Piet Retief up to N17 near Warburton
Distance	139 km
Description	Single carriageway with gravel shoulders.
Condition of the road	Fair but uneven in places.
Comments	No construction.
Duration of work	
Contact for Routine Road Maintenance	Tony Mathebula 071 670 0656

National Route	R33
Section	From N17 near Warburton, over Carolina up to N4 near Belfast
Distance	89 km
Description	Single carriageway with gravel shoulders.
Condition of the road	Fair but uneven in places.
Comments	Construction completed
Duration of work	
Contact for Routine Road Maintenance	Timothy Maselesa 082 807 1089

National Route	R33
Section	Piet Retief to N17
Distance	
Description	
Condition of the road	
Comments	Reseal & Reconstruction work – Stop/Go
Duration of work	April 2012
Contact for Routine Road Maintenance	Pieter Sutherland 083 310 5395

National Route	R33 Section 8
Section	N17 to Carolina
Distance	
Description	
Condition of the road	
Comments	Road work up until 15 December 2011 – No Stop/Go
Duration of work	Construction will resume January 2012
Contact for Routine Road Maintenance	

National Route	R35
Section	Amersfoort over Bethal up to Middelburg
Distance	156 km
Description	Single carriageway with gravel shoulders.
Condition of the road	Fair to poor, Surface failures from Amersfoort to Morgenzon. It is very poor between Amersfoort and Morgenzon
Comments	No construction.
Duration of work	
Contact for Routine Road Maintenance	Timothy Maselesa 082 807 1089

National Route	R35 Section 2
Section	Bethal to Middelburg
Distance	
Description	
Condition of the road	
Comments	Road work up until 15 December 2011 – No Stop/Go
Duration of work	Construction will resume January 2012
Contact for Routine Road Maintenance	

National Route	R36 – R71 – R526 – R40
Section	Bandelierskop –Soekmekaar –Mooketsi – Modjadjikloof (Duiwelskloof) – Tzaneen – Gravelotte – Mica – Klaserie (New Mpumalanga Border)
Distance	197 km
Description	Two-lane narrow single carriageway with gravel shoulders in places.
Condition of the road	Good.
Comments	No Construction only Routine Maintenance
Duration of work	
Contact for Routine Road Maintenance	Gustav Fouche 082 780 2391

National Route	R36
Section	Tzaneen to Soekmekaar
Distance	
Description	
Condition of the road	
Comments	Reconstruction work – Stop/Go till 15 December 2011
Duration of work	June 2012
Contact for Routine Road Maintenance	Bertie Brits 083 303 4418

National Route	R37
Section	Polokwane (Pietersburg) up to Mpumalanga border north of Burgersfort
Distance	160 km
Description	Single carriageway with gravel shoulders.
Condition of the road	Fair
Comments	Patching, Reseal shoulder work.
Duration of work	Routine Road Maintenance teams may be encountered. Patching
Contact for Routine Road Maintenance	George Brand 082 555 8493

National Route	R37
Section	Burgersfort to Lydenburg
Distance	57 km
Description	Single carriageway road with paved shoulders.
Condition of Road	Variable but generally fair.
Comments	No construction.
Duration of Work	
Contact for Routine Road Maintenance	Dries Grundlingh 083 269 3029

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered.

National Route	R37
Section	Lydenburg over Sabie to Nelspruit
Distance	86Km
Description	Single carriageway road with narrow shoulders.
Condition of Road	Fair
Comments	No construction
Duration of Work	
Contact for Routine Road Maintenance	Dries Grundlingh 083 269 3029

National Route	R38
Section	Bethal to Hendrina
Distance	43 km
Description	Single carriageway with gravel shoulders.
Condition of the road	Fair to poor and uneven in places
Comments	No construction.
Duration of work	
Contact for Routine Road Maintenance	Timothy Maselesa 082 807 1089

National Route	R38
Section	Hendrina over Carolina up to R40 near Barberton
Distance	171km
Description	Single carriageway with gravel shoulders.
Condition of the road	Fair to poor and uneven in places.
Comments	No construction.
Duration of work	
Contact for Routine Road Maintenance	Timothy Maselesa 082 807 1089

National Route	R38
Section	Carolina to Barberton
Distance	
Description	
Condition of the road	
Comments	Repair and Reseal work – Stop/Go from Carolina to Badplaas
Duration of work	October 2013
Contact for Routine Road Maintenance	Peter 082 558 9176

National Route	R40
Section	White River to Hazyview
Distance	
Description	
Condition of the road	
Comments	Reseal work – Stop/Go
Duration of work	July 2012
Contact for Routine Road Maintenance	Zaaid 082 810 4806

National Route	R40
Section	Hazyview to Bushbuck Ridge
Distance	
Description	
Condition of the road	
Comments	Upgrade – All Stop/Go will be removed by 15 December 2011
Duration of work	
Contact for Routine Road Maintenance	Joahn van Staden 082 303 7367

National Route	R40
Section	R533 to Hoedspruit
Distance	
Description	
Condition of the road	
Comments	Reseal work – Stop/Go
Duration of work	July 2012
Contact for Routine Road Maintenance	Eugene 082 902 8047

National Route	R40
Section	Hoedspruit to Mica
Distance	
Description	
Condition of the road	
Comments	Reseal work – Stop/Go
Duration of work	July 2012
Contact for Routine Road Maintenance	Johan 082 925 5261

National Route	R40
Section	North of White River to Klaserie (New Mpumalanga Border)
Distance	116 km
Description	Single carriageway with gravel shoulders in places.
Condition of Road	Fair
Comments	No construction.
Duration of Work	
Contact for Routine Road Maintenance	Dries Grundlingh 083 269 3029

National Route	R40
Section	Nelspruit to Barberton
Distance	45 km
Description	Upgraded single carriageway with climbing lanes in places and paved shoulders. Portion between Hilltop and Barberton still under construction, see2) below
Condition of Road	Very good and completed from Nelspruit to Hilltop Pass but fair to poor where construction work is still in progress towards Barberton. Road surfaces varying from well- kept gravel deviations to temporary all weather surfaces, but with no lane markings.
Comments	Construction completed. Now on the defect liability period.
Duration of Work	No construction
Contact for Routine Road Maintenance	Dries Grundlingh 083 269 3029

National Route	R61
Section	1 (East Cape/West Cape Border to Aberdeen)
Distance	74.5 km
Description	Single carriageway road
Condition of Road	Good
Comments	
Contact for Routine Road Maintenance	Johan Dorfling 082 847 6615

National Route	R61
Section	Bethesda (N9 Intersection) to Cradock (N10 Intersection)(section 2)
Distance	85.8 km
Description	A narrow 2-lane single carriageway with gravel shoulders over most of the length.
Condition of Road	Fair.
Comments	Construction is in progress from Wapadsberg for 17Km towards Cradock. At least 2(two) STOP/GO operations can be encountered. Speed restrictions of 60km/h are applicable and no overtaking will be possible in these STOP /GO section. Motorists must be aware of wild animals on the rest of road section.
Duration of Work	Jan 2012
Contact for Routine Road Maintenance	Gert de Lange 076 413 2989
Contact for Construction works	Ivor Floyd 083676 0132

National Route	R61
Section	Cradock (N10 Intersection) to Tarkastad (section 3)
Distance	74.5 km
Description	A narrow 2-lane single carriageway with gravel shoulders
Condition of Road	0-24km Good 24-75kmFair
Comments	No construction but motorist may encounter occasional short-term closures over short sections for routine maintenance. Motorist to be aware of wild animals in rural areas and pedestrians in urban area at Cradock and Tarkastad.
Contact for Routine Road Maintenance	Gert de Lange 076 413 2989

National Route	R61
Section	Tarkastad to Queenstown (section 4)
Distance	63.1km
Description	A narrow 2 lane single carriageway with gravel shoulders.
Condition of Road	Fair.
Comments	No construction but motorists may encounter occasional short-term closures over short sections for routine maintenance. Motorists to be aware of wild animals in rural areas and pedestrians in urban areas of Cradock and Queenstown.
Contact for Routine Road Maintenance	Gert de Lange 076413 2989

National Route	R61
Section	Queenstown (N6) to Cofimvaba
Distance	60Km
Description	A 2-lane single carriageway with wide paved shoulders
Condition of Road	Good
Comments	No construction but motorists may encounter occasional short-term closures over short sections for routine maintenance. Motorists to be aware of pedestrians and stray animals
Contact for Routine Road Maintenance	Kobus Vermeulen 082 304 6566

National Route	R61
Section	Cofimvaba to Engcobo
Distance	92 km
Description	Narrow 2 lane single carriageway with limited gravel shoulders.
Condition of Road	Fair to good.
Comments	Motorists to be aware of pedestrians and stray animals. No Construction but motorist may encounter occasional short term closures on short sections for routine maintenance.
Duration of Work	
Contact for Routine Road Maintenance	Kobus Vermeulen 082 304 6566

National Route	R61
Section	Engcobo to Mthatha
Distance	49 km
Description	Narrow 2 lane single carriageway with limited gravel shoulders.
Condition of Road	Fair to good
Comments	No construction but motorists may encounter occasional short-term closures over short sections for routine maintenance and construction works at the Mthatha airport and the R61/N2 Bypass intersections. Motorists to be aware of pedestrians and stray animals.
Contact for Routine Road Maintenance	Kobus Vermeulen 082 304 6566

National Route	R61
Section	Mthatha to Port St Johns
Distance	74 km
Description	A 2-lane single carriageway, with surfaced shoulders.
Condition of Road	Fair.
Comments	Construction works are in progress from Libode to Port St Johns. Road markings and minor seal repair are in progress.. Motorist must also be aware of reduced speed limits of 60km/h are imposed through sections which require maintenance or minor repairs. Dwelling in Tombo commenced in Oct 2011. Estimated completion April 2013
Duration of work	December 2011
Contact for Routine Road Maintenance	Kobus Vermeulen 082 304 6566
Contact for Construction works	Basil Sparg 079 677 7782

National Route	R61 (Wild Coast)
Section	Ntafufu River to Lusikisiki
Distance	18 Km
Description	Two-lane Single carriageway with Passing lanes
Condition of Road	Good
Comments	Motorist to be aware of pedestrians and animals. The road is winding.
	Reseal to commence Oct 2011 (\pm 20km)
Comment	Reseal has commenced in Oct 2011. Estimated completion June 2012. Traffic accommodation by means of Stop-Go's during daylight hours.
Contact for Routine Road Maintenance	Kobus Vermeulen 082 304 6566

National Route	R61
Section	Mtamvuna River (Provincial Boundary) to Port Shepstone
Distance	45 km
Description	Two-lane single carriageway with passing lanes.
Condition of Road	Good.
Comments	
Contact for Routine Road Maintenance	Amit Bhoora 082 442 9646

National Route	R71
Section	Polokwane (Pietersburg) – Magoebaskloof – Tzaneen
Distance	89 kms
Description	Two-lane narrow single carriageway with gravel shoulders.
Condition of the road	Fair.
Comments	No construction.
Duration of work	
Contact for Routine Road Maintenance	Oakley van Eyk 082 900 5345

National Route	R71 Section 1
Section	Polokwane to Boyne to Tzaneen
Distance	Km 6-39
Description	
Condition of the road	
Comments	Reseal work
Duration of work	March 2012
Contact for Routine Road Maintenance	Oakley van Eyk 082 900 5345

National Route	R71 Section 1
Section	Tzaneen to Veekraal
Distance	Km 39-88
Description	
Condition of the road	
Comments	Partial Reconstruction & 2 Permant Stop/Go
Duration of work	November 2013
Contact for Routine Road Maintenance	Oakley van Eyk 082 900 5345

National Route	R71 Section 2
Section	Tzaneen to Gravelotte
Distance	Km 0 – 52
Description	
Condition of the road	
Comments	Reseal work
Duration of work	June 2012
Contact for Routine Road Maintenance	Oakley van Eyk 082 900 5345

National Route	R81
Section	Polokwane (Pietersburg) – Mooketsi – Giyani
Distance	149 km
Description	Two-lane narrow single carriageway with gravel shoulders.
Condition of the road	Fair.
Comments	Patching, Reseal shoulders.
Duration of work	March 2012
Contact for Routine Road Maintenance	Oakley van Eyk 082 900 5345

National Route	R81
Section	Polokwane to Munnik
Distance	
Description	
Condition of the road	
Comments	Reconstruction work – Stop/Go
Duration of work	September 2012
Contact for Routine Road Maintenance	Fanie Mini 082 775 0931

National Route	R81
Section	Munnik to Giyani
Distance	
Description	
Condition of the road	
Comments	Reseal work
Duration of work	January 2012
Contact for Routine Road Maintenance	Oakley van Eyk 082 900 5345

National Route	R101
Section	Middelfontein Interchange (Modimole (Nylstroom)) to Mookgopong (Naboomspruit)
Distance	30 km
Description	Two-lane single carriageway with passing lanes.
Condition of Road	Good.
Comments	Routine Road Maintenance teams may be encountered. Patching. .
Duration of Work	
Contact for Routine Road Maintenance	George Brand 082 555 8493

National Route	R101
Section	Mookgopong (Naboomspruit) to Mokopane (Potgietersrust)
Distance	68km
Description	Two-lane single carriageway with paved shoulders and passing lanes in places.
Condition of Road	Fair
Comments	Routine Road Maintenance teams may be encountered. Patching. .
Duration of Work	
Contact for Routine Road Maintenance	George Brand 082 555 8493

National Route	R101
Section	Mokopane (Potgietersrus) to southern outskirts of Polokwane (Pietersburg)
Distance	51km
Description	Two-lane single carriageway with paved shoulders and passing lanes in places.
Condition of Road	Fair
Comments	
Duration of Work	Routine Road Maintenance teams may be encountered. Patching. .
Contact for Routine Road Maintenance	George Brand 082 555 8493

National Route	R104 (P154-1& P154-2)
Section	Pretoria-Bronkhorstspuit-Mpumalanga Border
Distance	64.28 Kms
Description	2-lane single carriageway with narrow gravel shoulders
Condition of the road	Fair/Poor uneven in places
Comments	No construction.
Duration of work	
Contact for Routine Road Maintenance	Philip Fourie 083 410 2601

National Route	R300
Section	Swartklip Interchange to Stellenberg Interchange
Distance	16.1 km
Description	Three-lane dual carriageway with paved shoulders.
Condition of Road	Good
Comments	No construction works
Duration of Work	
Contact for Routine Maintenance	Heuppschenne Lekay 082 782 9155

National Route	R510
Section	North West Border - Thabazimbi – Lephala (Ellisras) – Monte Christo
Distance	253 km
Description	Two-lane single carriageway with gravel shoulders
Condition of the road	Good.
Comments	No construction
Duration of work	
Contact for Routine Road Maintenance	Stephan du Plessis 084 491 1165

National Route	R521
Section	Polokwane (Pietersburg) – Dendron - Vivo
Distance	103 km
Description	Two-lane single carriageway.
Condition of the road	Fair. Gravel shoulders.
Comments	Routine Road Maintenance teams may be encountered. Patching. .
Duration of work	
Contact for Routine Road Maintenance	George Brand 082 5558493

National Route	R523
Section	Vivo - Waterpoort – Masekwaspoort
Distance	75 km
Description	Two-lane single carriageway.
Condition of the road	Good
Comments	Routine Road Maintenance teams may be encountered. Patching. .
Duration of work	
Contact for Routine Road Maintenance	George Brand 082 5558493

National Route	R555
Section	Witbank to Middelburg
Distance	28 km
Description	A 2-lane single carriageway road with narrow gravel shoulders
Condition of Road	Fair
Comments	No construction.
Duration of work	
Contact for Routine Road Maintenance	Philip Fourie 083 410 2601

National Route	R570 (P133/1)
Section	N4 to Malalane Gate
Distance	3 km
Description	Single carriageway with paved shoulders.
Condition of Road	Fair, uneven in places.
Comments	No construction.
Duration of work	
Contact for Routine Road Maintenance	Dries Grundlingh 083 269 3029

National Route	R570 (P80/1)
Section	N4 to Jeppes Reef Border Post
Distance	41 km
Description	Single carriageway with gravel shoulders.
Condition of Road	Fair, but uneven in places.
Comments	No construction.
Duration of Work	
Contact for Routine Road Maintenance	Dries Grundlingh 083 269 3029

National Route	R571 (D2683)
Section	N4 to Coopersdal
Distance	21 km
Description	Single carriageway with gravel shoulders.
Condition of Road	Fair, uneven in places
Comments	No construction.
Duration of Work	
Contact for Routine Road Maintenance	Dries Grundlingh 083 269 3029

National Route	R571 (D797)
Section	One Tree Hill (P80/1) to Tonga (D2948)
Distance	27 km
Description	Single carriageway with gravel shoulders.
Condition of Road	Fair to poor, and uneven in places.
Comments	No construction.
Duration of Work	
Contact for Routine Road Maintenance	Dries Grundlingh 083 269 3029

National Route	R571 (D2948)
Section	Tonga (D797) to Mangweni (P179/1)
Distance	10 km
Description	Single carriageway with paved shoulders.
Condition of Road	Fair to satisfactory.
Comments	No construction.
Duration of Work	
Contact for Routine Road Maintenance	Dries Grundlingh 083 269 3029

National Route	R572
Section	Monte Christo – Tom Bourke
Distance	95 kms
Description	Two-lane single carriageway.
Condition of the road	Fair. Gravel shoulders.
Comments	Seal work – Stop/Go up till 15 December 2011.
Duration of work	
Contact for Routine Road Maintenance	Wimpie van Rensburg 082 906 0150

NATIONAL BORDER CONTROL POSTS

Botswana Border

Border Post	Location	Description	Condition	Opening Times
Twee Rivieren	Situated in the Kgalagadi Cross Border National Park	Single carriageway gravelled road.	Fair	08h00 to 16h30
Gemsbok	Between Upington and Botswana	Single carriageway gravelled road.	Fair	08h00 to 16h30
Middelputs	Between Van Zylsrus and Botswana	Single carriageway gravelled road.	Fair	08h30 to 16h30
McCarthy's Rest	Route R380 between Kathu and Thshabon (Botswana)	Single carriageway gravelled road.	Fair	08h00 to 16h30
Makopong	Route R379 between Bryburg and Botswana	Single carriageway gravelled road.	Fair	07h30 to 16h00
Bray	Route R378 between Bryburg and Botswana	Single carriageway gravelled road.	Fair	07h30 to 16h00
Boshoek	Route R375 between Bryburg and Botswana	Single carriageway gravelled road.	Fair	07h30 to 16h00
Magobistad	Between Mafikeng & Botswana	Single carriageway gravelled road.	Fair	07h30 to 16h30
Ramatlabama	Between Mafikeng & Botswana	Single carriageway paved road.	Good	07h00 to 20h00
Skilpadshok	N4 Platinum – Lobatse	Single carriageway paved road.	Good	07h00 to 19h30
Swartkopfontein	Between Zeerust & Gaborone	Single carriageway paved road.	Good	07h00 to 19h00
Kopfontein	Between Zeerust & Gaborone	Single carriageway paved road.	Good	07h00 to 22h00
Derdepoort	Between Rustenburg & Botswana	Single carriageway gravelled road.	Poor	07h00 to 19h00
Stockpoort	From Ellisras to Botswana	Single carriageway paved road.	Good	08h00 to 16h00
Groblers Bridge	From Potgietersrus on N11 to Botswana	Single carriageway paved road.	Good	08h00 to 18h00
Zanzibar	Between Alldys & Selebi-Pikwi	Single carriageway gravelled road.	Fair	08h00 to 16h00
Platjan	Between Alldys & Selebi-Pikwi	Single carriageway gravelled road.	Fair	08h00 to 16h00
Pondrift	From Alldys on R521 to Botswana	Single carriageway paved road.	Good	08h00 to 16h00

Namibia Border

Border Post	Location	Description	Condition	Opening Times
Alexander Bay	Between Alexander Bay and Oranjemund (Namibia)	Single carriageway paved road.	Good	06h00 to 22h00
Violsdrift	Route N7/B1 between Springbok and Keetmanshoop (Namibia)	Single carriageway paved road.	Good	24 hours
Onseepkans	Route R358/C10 between Pofadder and Karasburg	Single gravelled road with single traffic lane bridge over Orange River Bridge	Fair	08h00 to 16h30
Nakop	Route N10/B3 between Upington and Karasburg (Namibia)	Single carriageway paved road with gravelled shoulders. New Border Control Post situated 1 km from actual border with Namibia.	Good	24 hours
Noenieput	Between Upington and Aroab (Namibia)	Single carriageway gravelled road.	Fair	08h00 to 16h30
Rietfontein	Route R31/C16 between Askam and Aroab (Namibia)	Single carriageway gravelled road.	Fair	08h00 to 16h30

Zimbabwe Border

Border Post	Location	Description	Condition	Opening Times
Beitbridge	On N1 between RSA and Zimbabwe	Single carriageway paved road.	Fair	Passengers: 24hrs Commercial: 24hrs

Mozambique Border

Border Post	Location	Description	Condition	Opening Times
Pafuri	In Kruger National Park, nearest route is R525, east/west direction ± 25 km adrift)	Single carriageway paved road under construction.	Fair	08h00 to 16h00
Lebombo	On N4 between Nelspruit and Maputo	Single carriageway paved road.	Good	06h00 to 22h00
Kosibay (Farazela)	On R22 between RSA and Mozambique	Single carriageway paved road with narrow paved shoulders.	Good	06h00 to 1800

Swaziland Border

Border Post	Location	Description	Condition
Mananga	On R571 between Komatipoort and Swaziland	Single carriageway paved road.	Fair
Jeppe's Reef	On R570 between Malelane and Swaziland	Single carriageway paved road.	Good
Josefsdal	On R40 between Barberton and Piggs Peak	Single carriageway gravelled road.	Poor
Oshoek	On N17 between Ermelo and Manzini	Single carriageway paved road.	Good
Waverley	Off R33 between RSA and Swaziland	Single carriageway paved road.	Good
Nerston	On R65 between RSA and Swaziland	Single carriageway paved road.	Fair
Emhlalatinhi	Between Piet Retief and Swaziland	Single carriageway paved road.	Good
Bothashoop	Between Piet Retief and Swaziland	Single carriageway gravelled road.	Fair
Mahamba	Between Piet Retief and Swaziland	Single carriageway paved road.	Good
Onverwacht	D1936 off N2 (KwaZulu-Natal)	Single carriageway paved road.	Good
Golela/Lavumisa	P 720 off N2 (KwaZulu-Natal)	Single carriageway paved road.	Good

Lesotho Border

Border Post	Location	Description	Condition
Monantsapas	R 57/S1579 (Free State)	Single carriageway paved road	Fair to good
Caledonspoort	P 92/1 (Free State)	Single carriageway paved road	Fair to poor
Ficksburg Bridge	R 26 / P75/1 (Free State)	Single carriageway paved road	Fair
Peka Bridge	S 388 / S 306 (Free State)	Single carriageway gravel road	Poor
Maseru Bridge	N8 (Free State)	Single carriageway paved road.	Fair
Van Rooyen's Gate	P66/1 (Free State)	Single carriageway paved road	Fair
Sepapu's Gate	S4 (Free State)	Single carriageway gravel road	Poor
Makhaleng Bridge	S2 (Free State)	Single carriageway gravel road	Very Poor
Telle Bridge	R 392 (from Sterkspruit in the Eastern Cape)	Single carriageway paved road.	Good
Ongeluksnek	Eastern Cape: Off R 56. Closest towns are Mount Fletcher and Matatiele	Gravel approach road.	Poor to very poor. Only suitable to 4x4 vehicles beyond the border post.
Qacha's Nek	Eastern Cape: Closest town Matatiele	Gravel approach road.	Poor
Ramaselitso Gate	Eastern Cape: Closest from Matatiele	Gravel approach road.	Poor
Sani Pass	P 318 (KwaZulu-Natal)	Gravel approach road	Fair but often only accessible to 4X4 vehicles beyond the border post.

THE SOUTH AFRICAN NATIONAL ROADS AGENCY SOC LTD

Contact Details

Head Office

48 Tambotie Avenue
Val de Grace
Pretoria, 0184
Tel. 012 844 8000
Fax 012 362 2117

Northern Region

38 Ida Street
Menlo Park
Pretoria, 0081
Tel. 012 426 6200
Fax 012 348 1680

Eastern Region

58 Van Eck Place
Mkondeni
Pietermaritzburg
Tel. 033 392 8100
Fax 033 386 6284 / 3365

Southern Region

NRA House
Southern Life Gardens
70 Second Avenue
Newton Park
Port Elizabeth
Tel. 041 398 3200
Fax 041 398 3222

Western Region

Parc du Cap
Building 5
Corner Mispel Street / Willie van Schoor Avenue
Bellville 7530
Tel. 021 957 4600
Fax 021 946 1630

Website: www.nra.co.za

E-mail: info@nra.co.za

Fraud Hot Line: 0800204558