

# Road Conditions

## December 2013 and January 2014

### N1

National Route	N1
Section	Old Oak Interchange to Rawsonville
Distance	64 km
Description	Two-lane dual carriageway with paved shoulders.
Condition of Road	Fair to Good.
Comments	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Maintenance	Heuppschenne Lekay 082 782 9155

National Route	N1
Section	Worcester to Laingsburg
Distance	156 km
Description	Single carriageway with paved shoulders. The road through Hex River Pass is a four-lane dual carriageway (four km) with an arrestor bed in the south-bound direction before the hairpin curve known as "Spookdraai". Stopping places are provided at regular intervals.
Condition of Road	Good.
Comments	A compulsory stop, manned by the Provincial Traffic Department, is in operation $\pm$ five km south of Touws River. An unmanned compulsory stop for heavy vehicles is also in operation on the south-bound carriageway in Hex River Pass. Motorists should also be alert to pedestrians and/or stray animals just north of De Doorns. Motorists should also be alert to hawkers selling alongside the road. It is illegal to stop and buy from the sellers.
Duration of Work	Ongoing
Contact for Routine Maintenance	Riaan Davids 082 553 4878

National Route	N1 - Sections 3 (km48.6) & 4 (km45)
Section	Hex River Pass to Monument River
Distance	71 km
Description	Single carriageway road with climbing lanes and with gravel shoulders.
Condition of Road	Good.
Comments	Construction work is in progress and concentrated between km56 (Section 3) and km45 (Section 4). During November 2013 motorists will encounter 3no 24hr STOP/GO closures. In these closures there will be asphalt patching, sand blasting and geotextile patching being done. Between km10 and km14 (section 4) we will also be doing in-situ recycling. This will also be one of the closures. Work on the slow lane from km62 to km63 (Section 3) direction Touwsrivier are also currently underway. Only one lane is available (direction Touwsrivier) and concrete barriers have been placed along the rehabilitation section. Once they start with the Base course the barriers will be removed and a day closure will be operated.
Duration of Work	Start 3 June 2013 - End 2 June 2014
Contact for Routine Road Maintenance	Riaan Davids (Qunu) 082 55 34 878 Alec Bester (MD Civils) 083 50 10 028

National Route	N1
Section	Laingsburg to Leeu-Gamka
Distance	124 km
Description	Single carriageway with paved shoulders. Stopping places are provided at regular intervals.
Condition of Road	Good.
Comments	Construction works between Laingsburg and Dwyka has been completed. Routine road maintenance teams may be encountered.  "Kanniedood" safety project is in operation on this section of road. A compulsory stop, manned by the Provincial Traffic Department, is in operation $\pm$ 15 km south of Leeu-Gamka. Motorists should be alert to pedestrians and/or stray animals crossing the road in the vicinity of Leeu-Gamka.
Duration of Work	Ongoing Routine Road Maintenance

Contact for Routine Maintenance	Jerome Buys 082 328 9422
National Route	N1
Section	Leeu-Gamka to Beaufort-West
Distance	75 km
Description	Single carriageway with paved shoulders. Stopping places are provided at regular intervals.
Condition of Road	Good.
Comments	Construction work between Leeu-Gamka and Beaufort-West is complete. Routine road maintenance teams may be encountered. Motorists should also be alert to pedestrians and/or stray animals in Beaufort-West.
Duration of Work	July 2010 to February 2012 (Ongoing Routine Road Maintenance)
Contact for Routine Road Maintenance	Jerome Buys 082 328 9422

National Route	N1
Section	Beaufort-West to Three-Sisters
Distance	97 km
Description	Single carriageway with paved shoulders. Stopping places are provided at regular intervals.
Condition of Road	Good.
Comments	Construction works are in progress between Nelspoort and Three Sisters:  Up to the end of November 2013, motorists can encounter one manually and traffic-light controlled Stop/Go section with waiting period on average 10 minutes. This section is a day and night closure. Motorists can also encounter one roving day closure with average waiting period of 10 minutes
Duration of Work	November 2011 to November 2013
Contact for Routine Maintenance	Jerome Buys 082 328 9422

National Route	N1
Section	Three-Sisters to Colesberg
Distance	236 km
Description	Single carriageway with paved shoulders. Stopping places are provided at regular intervals.
Condition of Road	Fair
Comments	Construction works are in progress between Bultfontein and Richmond:  Motorists can encounter up to three manually and traffic-light controlled Stop/Go sections with waiting period on average 10 minutes per section. These sections are day and night closures.  Rehab of Colesberg between Wolwefontein and Colesberg and new access interchange in Colesberg  N9 between Wolwefontein and Colesberg: Road open to two way traffic on N9 between Wolwefontein (km 63.9) and Colesberg with work on road shoulders except at one stop /go closure between km 72.4 and km 76.0 until 10 September 2013 for layerworks and surfacing. Speed restricted to 80kph along this section of N9 except through stop/go closure where the speed is reduced to 60kph.  N9/N1 Interchange at Colesberg: Two way traffic though Colesberg, but detours in place at entrance to Colesberg on N1 and at the N9 intersection. Speed limited to 60kph on N1 through Colesberg  Construction work is in progress between Colesberg and the Orange River bridge.  Construction work is in progress between Colesberg and the Orange River bridge.  During November 2013 motorists will encounter two day-night Stop/Go closures for half-width road reconstruction, from km 14 to km 19, and km 4 to km 8. There will also be one roving day closure for texture slurry.  Waiting time: 10-15 minutes at each closure.
Duration of Work	Jan 2013 until June 2014
Contact for Routine Maintenance	Dan Louw 083 383 8174

National Route	N1
Section	Orange River Provincial Boundary to Bloemfontein (Sydenham Interchange)
Distance	875 km
Description	A four-lane single carriageway freeway with paved shoulders. Beyond the Orange River provincial boundary, the road is a four-lane single carriageway with wide paved shoulders and sustained grades.
Condition of Road	Generally good.
Comments	Good. Road construction is being undertaken between Fonteintjie (Section 14, km39) and Wurasoord (Section 14, km92). Traffic will be accommodated by way of deviations. Caution of speed restrictions are encouraged when travelling on the deviations. No Stop/Go controls are envisaged.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Henk Diederik of the section south of Bloemfontein between Wurasoord and Sydenham Interchange 082 704 6559. Traffic will be accommodated by way of deviations. No Stop/Go controls are envisaged.
Duration of Work	1. Until November 2013 2. Until December 2014.
Contact for Routine Road Maintenance	Riaan Louwrens 074 601 8998

National Route	N1		
Section	Bloemfontein to Kroonstad		
Distance	189 km		
Description	Around Bloemfontein and extending northwards for some 15km, the road is a four-lane dual carriageway with wide paved shoulders. Thereafter it reduces to a four-lane single carriageway for the next 20kms, otherwise it is a two-lane single carriageway with paved shoulders and passing lanes on steep gradients. The last 10 km, known as the Kroonstad Bypass, is a four-lane dual carriageway.		
Condition of Road	Generally good.		
Comments	An improvement contract through Ventersburg is in progress. Traffic is being accommodated through parallel roads adjacent to the N1. Although through traffic will have priority, delays can be expected. Motorists should be alert to pedestrian and heavy vehicle activity through Ventersburg, where an urban speed restriction is in place.		
Duration of Work	Ventersburg realignment until July 2014.		
Contact for Routine Road Maintenance	Japie Taljaard 082 857 7175	Robert Fourie 076 140 8863	Attie Badenhorst 082 789 3533

National Route	N1		
Section	Kroonstad to Vaal River (Free State – Gauteng Provincial Boundary)		
Distance	102 km		
Description	Partly a single carriageway with alternating passing lanes in each direction and wide gravel shoulders, and partly a four-lane single carriageway, except for the 10 km portion beyond the Vaal Toll Plaza, where it becomes a four-lane dual carriageway with wide paved shoulders.		
Condition of Road	Good.		
Comments	No construction		
Duration of Work			
Contact for Routine Road Maintenance	Japie Taljaard 082 857 7175	Attie Badenhorst 082 789 3533	Robert Fourie 076 140 8863

National Route	N1
Section	Vaal River (provincial boundary) to Johannesburg
Distance	64 km
Description	Four-lane dual carriageway freeway with wide paved shoulders.
Condition of Road	Good.
Comments	Motorists should beware of pedestrian activity along the route. Additional street lighting has been installed at the Ennerdale Interchange.
Duration of Work	
Contact for Routine Road Maintenance	Herman du Plessis 082 721 4886

**For up to date traffic information on construction works on the Gauteng Freeway Improvement Project, please visit [www.i-traffic.co.za](http://www.i-traffic.co.za).**

National Route	N1 (GFIP)
Section	Misgund (Soweto) to Buccleuch
Distance	38 km

*Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered*

Description	Construction of six lanes and upgrade of Interchanges – Lane restriction in off peak hours
Comments	Ongoing
Duration of Work	

National Route	N1
Section	Section 20 & 14 <sup>th</sup> Avenue to Buccleuch
Distance	
Description	Construction of lanes & upgrade of Interchanges
Condition of the road	
Comments	Lane closures at night
Duration of work	Ongoing
Contact for Routine Road Maintenance	Hennie Kotze 083 283 6051

National Route	M1
Section	Buccleuch to Corlett Drive
Distance	
Description	Construction of lanes & upgrade of Interchanges
Condition of the road	
Comments	Lane closure off peak hours
Duration of work	Ongoing
Contact for Routine Road Maintenance	Hennie Kotze 083 283 6051

National Route	N1 (GFIP)
Section	Brakfontein to N4 Interchange
Distance	10 km
Description	Construction of six lanes and upgrade of Interchanges – Lane restriction in off peak hours
Comments	Expected completion April 2013 no construction
Duration of Work	

National Route	N1
Section	Pretoria (N4 Interchange) to Bela Bela (Warmbaths) (Platinum Toll highway)
Distance	94 km
Description	Six-lane dual carriageway freeway from Pretoria (Proefplaas Interchange) to Zambesi Interchange changing into four-lane dual carriageway freeway to Bela Bela. Mill and Replace operations in progress.
Comments	No construction
Duration of Work	
Contact for Routine Road Maintenance	Pt Ops 012 804 0044

National Route	N1
Section	Bela Bela to Polokwane (Great North Toll Road)
Distance	160 km
Description	Four-lane dual carriageway freeway from the Warmbaths/Settlers interchange to the Kranskop toll plaza. Four-lane single carriageway freeway from the Kranskop Toll Plaza to the N1/R71 interchange at Polokwane.
Comments	No Construction
Duration of Work	
Contact for Routine Road Maintenance	NTRV Danie Kotze 082 822 0902

National Route	N1
Section	Polokwane (Pietersburg) to Louis Trichardt
Distance	98 km
Description	Two-lane single carriageway with paved shoulders.
Condition of Road	Very good.
Comments	Routine Road Maintenance teams may be encountered
Duration of Work	
Contact for Routine Road Maintenance	George Brand 082 555 8493

National Route	N1
Section	Louis Trichardt to Masekwaspoort
Distance	28 km
Description	Two-lane single carriageway with passing/climbing lanes and no paved shoulders.
Condition of Road	Good.
Comments	Patching work – Routine Road Maintenance Teams may be encountered.
Duration of Work	
Contact for Routine Road Maintenance	George Brand 082 555 8493

National Route	N1
Section	Musina to Beit Bridge
Distance	15 km
Description	Two-lane single carriageway with paved shoulders
Condition of Road	Good
Comments	Patching work – Routine Road Maintenance Teams may be encountered.
Duration of Work	
Contact for Routine Road Maintenance	George Brand 082 555 8493

National Route	N1
Section	Masekwaspoort to Musina
Distance	62 km
Description	Two-lane single carriageway with passing lanes, but paved shoulders only on last 20 Km before Musina.
Condition of Road	Good.
Comments	Patching work – Routine Road Maintenance Teams may be encountered.
Duration of Work	
Contact for Routine Road Maintenance	George Brand 082 555 8493

## N2

National Route	N2
Section	Swartklip Interchange to Somerset-West
Distance	24 km
Description	Two-way dual carriageway with paved shoulders
Condition of Road	Good.
Comments	Routine road maintenance teams may be encountered
Duration of Work	Ongoing.
Contact for Routine Road Maintenance	Heuppschenne Lekay 082 782 9155

National Route	N2
Section	Somerset-West to Botriver
Distance	45 km
Description	Single carriageway road with narrow paved shoulders and climbing lanes are provided through Sir Lowry's Pass. A four (4)- lane single undivided carriageway road through Sir Lowry's Pass and Houwhoek Pass.
Condition of Road	Good.
Comments	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing.
Contact for Routine Road Maintenance	Heuppschenne Lekay 082 782 9155

National Route	N2
Section	Botriver to Caledon
Distance	30 km
Description	Single carriageway with paved shoulders and climbing lanes.
Condition of Road	Good.
Comments	Routine road maintenance teams may be encountered
Duration of Work	Ongoing.
Contact for Routine Road Maintenance	Pierre Terblanche 084 516 7121

National Route	N2
Section	Caledon to Riviersonderend
Distance	48 km
Description	Single carriageway with paved shoulders and climbing lanes.
Condition of Road	Good.
Comments	Routine road maintenance teams may be encountered
Duration of Work	Ongoing.
Contact for Routine Road Maintenance	Pierre Terblanche 084 516 7121

National Route	N2
Section	Riviersonderend to Swellendam
Distance	58 km
Description	Single carriageway with paved shoulders.
Condition of Road	Good.
Comments	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing.
Contact for Routine Road Maintenance	Pierre Terblanche 084 516 7121

National Route	N2
Section	Swellendam to Riversdale
Distance	82 km
Description	Single carriageway with paved shoulders.
Condition of Road	Good.
Comments	Routine road maintenance teams may be encountered.
Duration of Work	. Ongoing routine road maintenance.
Contact for Routine Road Maintenance	Pierre Terblanche 084 516 7121

National Route	N2
Section	Riversdale to Mossel Bay
Distance	82 km
Description	Single carriageway with paved shoulders.
Condition of Road	Good.
Comments	Routine road maintenance teams may be encountered.  Construction in progress between Gouritzmouth and Mosselbay: work and will be day and night. Delays of about 10 minutes may be experienced at each closure.  Work will also take place on 2 lanes of the undivided four lane section of the road between Herbetsdale intersection (km 78) and Mosselbay (km 82). On this section 2 way traffic is accommodated on the remaining two lanes and no significant delays are expected.  Up to two shoulder closures may also be in operation. Two way traffic will be accommodated at these shoulder closures and no delays are expected.
Duration of Work	October 2012 until July 2013
Contact for Routine Road Maintenance	Johan Nel 082 373 3812

National Route	N2
Section	Mossel Bay to George
Distance	51 km
Description	A four-lane dual carriageway.
Condition of Road	Good.
Comments	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing routine road maintenance.
Contact for Routine Road Maintenance	Johan Nel 082 373 3812

National Route	N2
Section	George to Knysna
Distance	54 km
Description	Single carriageway with paved shoulders and climbing lanes.
Condition of Road	Good with the exception of Knysna Lagoon Bridge to Knysna Town. From the Knysna Lagoon Bridge to Knysna town the road is uneven and very narrow with no overtaking opportunities.
Comments	Construction of Bridge Balustrades is complete. Motorists should be alert to pedestrians and/or stray animals in the vicinity of Knysna Lagoon. Motorists should also be alert to hawkers selling alongside the road. It is illegal to stop and buy from the sellers.
Duration of Work	Construction complete. Ongoing routine road maintenance.
Contact for Routine Road Maintenance	Johan Nel 082 373 3812

National Route	N2
Section	Knysna to Plettenberg Bay
Distance	39 km
Description	Single carriageway with narrow paved shoulders.
Condition of Road	Good.
Comments	Routine road maintenance teams may be encountered. Motorists should be alert to pedestrians and/or stray animals in the vicinity of the informal settlement in Knysna, as well as in the vicinity of Plettenberg Bay.
Duration of Work	Ongoing.
Contact for Routine Road Maintenance	Johan Nel 082 373 3812

National Route	N2
Section	Plettenberg Bay to Natures Valley T-Junction (Sout River)
Distance	20 km
Description	Single carriageway with narrow paved shoulders and climbing lanes.
Condition of Road	Good.
Comments	Motorists should be alert to pedestrians and/or stray animals in the vicinity of the Craggs.
Duration of Work	
Contact for Routine Road Maintenance	Johan Nel 082 373 3812

National Route	N2
Section	Natures Valley to Storms River
Distance	40 km
Description	A two-lane single carriageway with surfaced shoulders.
Condition of Road	Good
Comments	Toll Road
Contact for Routine Road Maintenance	Jaco Klopper 083 446 8501

National Route	N2
Section	Storms River Town to Elands River
Distance	14 km
Description	A two-lane single carriageway with shoulders.
Condition of Road	Good
Comments	Toll Road
Contact for Routine Road Maintenance	Jaco Klopper 083 446 8501

National Route	N2
Section	Elands River to Gamtoos
Distance	98 km
Description	A two-lane single carriageway with shoulders.
Condition of Road	Good
Contact for Construction	Jaco Klopper 083 446 8501

National Route	N2
Section	Gamtoos River to Van Stadens River
Distance	19 km
Description	14,7 km of 2-lane single carriageway and 4.3 km of dual carriageway with surfaced shoulders.
Condition of Road	Good
Comments	
Duration of Work	
Contact for Routine Road Maintenance	Jaco Klopper

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered



Maintenance	083 446 8501
National Route	N2
Section	Van Stadens River Bridge
Distance	
Description	Dual carriageway with 2 lanes per direction. However, due to some concrete repairs being undertaken on the bridge, the slow lanes will be closed to traffic on both sides of the bridge.
Condition of Road	Good
Comments	Speed restrictions will be in place where lane closures are in place on the bridge
Duration of Work	December 2013
Contact for Construction	Loet Smit 082 587 9040
Contact for Routine Road Maintenance	Jaco Klopper 083 446 8501

National Route	N2
Section	Van Stadens River to Port Elizabeth (Markman)
Distance	57 km
Description	Dual carriageway with 2 lanes per direction.
Condition of Road	Good
Contact for Routine Road Maintenance	Jaco Klopper 083 446 8501

National Route	N2
Section	Port Elizabeth (Coega IDZ ) to Colchester
Distance	14Km
Description	14km freeway and 10km 2 lane under construction.
Condition of Road	Fair, but narrow and uneven in places and prone. Under construction
Comments	At Colchester construction works are in progress with limited impact on road users. Caution should be exercised at construction vehicle entry and exiting positions. 60 – 80 kph restrictions are in place for working hours
Duration of Work	Until Sept 2014
Contact for construction project	Jan Verduyn 082451 0346
Contact for Routine Road Maintenance	Jaco Klopper 082 309 2311

National Route	N2
Section	Fish river to Keiskamma Pass
Distance	27 km
Description	A 2-lane single carriageway mostly on bypass roads
Condition of Road	Under construction
Comments	Road under construction with reduced speed restriction of 60-80km/h users to be aware of turning trucks
Duration of Work	March 2013
Contact for Routine Road Maintenance	Siyam Rune 082 309 2311
Contact for Construction project	Harold Webster 083 452 6343: Either permanent or temp replaced by Andre Bardenhorst

National Route	N2
Section	Keiskamma River to Green River
Distance	23 km
Description	A 2-lane single carriageway under construction on bypass roads and new construction.
Condition of Road	Under construction.
Comments	Speed reduction of 60 and 80km/h will be encountered with Stop/Go resulting in up to 20 minutes delay. Please look out for turning trucks. Road users are requested to exercise caution where construction workers are encountered next to the roadway
Duration of Work	Until September 2014?
Contact for Routine Road Maintenance	Siyam Rune 082 309 2311
Contact for Construction	Ian Posselt 071 993 6399

National Route	N2
Section	King Williams Town to East London (Gonubie)
Distance	60 km
Description	A 4-lane dual carriageway
Condition of Road	Fair with road failures after rain
Comments	Short-term road narrowing for repairs could be encountered, especially between King Williams Town and East London.
Duration of Work	
Contact for Routine Road Maintenance	Siyam Rune 082 309 2311

National Route	N2
Section	King Williams Town to East London (Gonubie)
Distance	60 km
Description	A 4-lane dual carriageway
Condition of Road	Fair
Comments	Short-term road narrowing for repairs could be encountered, especially between King Williams Town and East London.
Duration of Work	
Contact for Routine Road Maintenance	Siyam Rune 082 309 2311

National Route	N2
Section	East London (Gonubie) to Kei River
Distance	60 km
Description	The first 2km is a 4-lane dual carriageway. Thereafter it becomes a 2-lane single carriageway with wide paved shoulders. Climbing lanes are provided on some steep grades.
Condition of Road	The condition is fair to good, except for the section between Gonubie and Brakfontein interchanges where the riding quality is uneven. Construction from Nov 2011 on this section. With reduce speed restrictions of 60km/h . Stop-Go situation with a $\pm$ 10 minute waiting period
Duration of Construction	Construction will continue to November 2013
Contact for Construction	Nick Kitsopoulos 082 576 4667
Contact for Routine Road Maintenance	Mike Coetzee 082 321 7946

National Route	N2
Section	Kei River to Dutywa
Distance	68 km
Description	Single carriageway road with paved shoulders and climbing lanes.
Condition of Road	The condition is good.
Comments	
Duration of work	
Contact for Routine Road Maintenance	Mike Coetzee 082 321 7946

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

National Route	N2
Section	Dutywa to Mthatha
Distance	85 km
Description	Single carriageway road with paved shoulders and climbing lanes. Road surface failures / potholes may occur especially after heavy rains between the SitebeKomkhulu intersection and Mthatha, which is under construction and where lane reduction, closures and speed reduction will be encountered.
Condition of Road	Fair
Duration of work	April 2013
Contact for Routine Road Maintenance	Mike Coetzee 082 321 7946
Contact for Construction Project	Renier Speyers 0824409148

National Route	N2
Section	Mthatha to Mount Ayliff
Distance	130 km
Description	A 2 lane single carriageway with climbing lanes and paved shoulders.
Condition of Road	The condition of the road between km 54 to km 70 is fair however routine maintenance may be encountered.
Contact for Routine Road Maintenance	Ernest Tellrhuber 078 389 6499

National Route	N2
Section	Mount Ayliff to Brookes Nek ( Provincial Boundary)
Distance	40 km
Description	A 2 lane single carriageway with climbing lanes and paved shoulders.
Condition of Road	The condition of the road between km 54 to km 70 is fair however routine maintenance may be encountered.
Comments	The rehabilitation of this section of the N2 has started. Speed reductions and Stop/Go's situations will be encountered, with delays of up to 20 minutes to be expected.
Duration	October 2014
Contact for Construction	Gerard Downing 083 262 7143
Contact for Routine Road Maintenance	Ernest Tellrhuber 078 389 6499

National Route	N2
Section	Brookes Nek (provincial boundary) to Port Shepstone
Distance	135 km
Description	This first section of the N2 in KZN is a two-lane single carriageway with narrow paved shoulders. Climbing lanes are provided on all the severe grades with the exception of a short 6 km section, 26 km north of Kokstad.
Condition of Road	Good.
Comments	<ol style="list-style-type: none"> <li>1. Construction of the Singisi Cutting truck stop between km 26 and km 32 is in progress. Reduced speeds are signposted.</li> <li>2. Motorists to be aware of construction activity at the Staffords Post Interchange (N2/R56). Traffic will be diverted onto a temporary deviation during the construction phase. Reduced speeds are signposted.</li> <li>3. Road works between Murchison and Port Shepstone are in progress. Speed restrictions are in place. Motorists to be aware of construction vehicles, pedestrians and school children. Traffic calming measures in place at Murchison Hospital.</li> </ol>
Duration of Work	<ol style="list-style-type: none"> <li>1. Completion by December 2013.</li> <li>2. Completion by March 2015.</li> <li>3. Completion by June 2015.</li> </ol>
Contact for Routine Road Maintenance	Amit Bhoora 082 442 9646

National Route	N2
Section	Port Shepstone to Durban (N2/N3 Interchange)
Distance	114 km
Description	The first 20 km is a single carriageway road with three lanes of traffic and narrow paved shoulders allowing overtaking opportunities. Thereafter the road becomes a four-lane dual carriageway with wide paved shoulders. The last 17 km leading into Durban has 3 lanes in each direction and is heavily trafficked.
Condition of Road	Good.
Comments	The repairs of new interchange ramp at Mnini Interchange are ongoing.
Duration of Work	Until December 2013.
Contact for Routine Road Maintenance	Amit Bhoora 082 442 9646 (Port Shepstone to Hibberdene) Lucille Mabena 083 537 3430 (Route Manager) and Jared Reddy 082 478 0065 24hr number 074 583 3576 (Hibberdene to Durban)

National Route	N2
Section	Durban to Empangeni
Distance	162 km
Description	For 71 km, up to Stanger, the road is a four-lane dual carriageway. For the next 52 km, up to the Mtunzini Toll Plaza, the road is a four-lane undivided carriageway with paved shoulders. The remaining portion is a single carriageway with alternating passing opportunities.
Condition of Road	Good.
Comments	<ol style="list-style-type: none"> <li>1. Major improvements to Umgeni Road Interchange will result in disruptions to traffic on the N2 and cross roads. Speed restrictions are signposted.</li> <li>2. A contract for the upgrading of the N2/M41 Mount Edgecombe Interchange to a free-flow systems interchange is in progress. Traffic will be accommodated on temporary deviations as from January 2014.</li> <li>3. Capacity improvements between Umdloti Interchange and Tongaat Toll Plaza are in progress. The project entails the addition of lanes over the project length from km 11.0 to km 21.0. Lane closures and reduced speeds are in place.</li> <li>4. Reconstruction of the Ballito Interchange is in progress. Speed restrictions are signposted.</li> <li>5. Resurfacing of 57 km from New Guelderland (Section 27, km 33) to Mtunzini Toll Plaza (Section 28, km 41.1) is in progress. Traffic will be restricted to single lanes in work zones.</li> </ol>
Duration of work	<ol style="list-style-type: none"> <li>1. Until September 2014.</li> <li>2. Until May 2016.</li> <li>3. Until September 2014.</li> <li>4. Until April 2014.</li> <li>5. Until October 2014</li> </ol>
Contact for Routine Road Maintenance	Lucille Mabena 083 537 3430 (Route Manager) and Jared Reddy 082 478 0065 24hr number 074 583 3576 (Durban to Umdloti) \ Bill Morris 083 655 4228 (Umdloti to Empangeni)

National Route	N2
Section	Empangeni to Pongola
Distance	250 km
Description	A 2-lane single carriageway with paved shoulders.
Condition of Road	Good
Comments	Repairs to some bridges on this section are ongoing. Speed restrictions and shoulder closures can be expected.
Duration of work	Until November 2013
Contact for Routine Road Maintenance	Gonie Govender 084 466 2198

National Route	N2
Section	Pongola to KwaZulu-Natal / Mpumalanga Border
Distance	38 km
Description	A 2-lane single carriageway road with climbing lanes on the steeper gradients.
Condition of Road	Good
Comments	No construction
Duration of work	
Contact for Routine Road Maintenance	Gonie Govender 084 466 2198

National Route	N2
Section	Mpumalanga Border north of Pongola to Piet Retief
Distance	44 km
Description	A two-lane single carriageway with narrow gravel shoulders.
Condition of Road	Good
Comments	No construction
Duration of Work	
Contact for Routine Road Maintenance	Hannelie Kruger 082 380 5264

National Route	N2
Section	Piet Retief to Ermelo
Distance	117 km
Description	A two-lane single carriageway with narrow gravel shoulders. First 7 kilometres is 4 lane undivided
Condition of Road	Good
Comments	No construction
Duration of Work	
Contact for Routine Road Maintenance	Hannelie Kruger 082 380 5264

### N3

National Route	N3
Section	Durban to Cedara (Hilton)
Distance	85 km
Description	This entire section is a multi-lane dual carriageway. The first 4km out of Durban carries heavy traffic with up to 5 lanes in each direction. The next 40 km, up to Cato Ridge, has 3 lanes in each direction with wide paved shoulders. The section between Cato Ridge and the end of the Pietermaritzburg Bypass (33 km) has a two-lane plus paved shoulder configuration, except on steep gradients to the east of Pietermaritzburg where climbing lanes are provided. The final 14 km to Howick incorporates the notorious, steeply graded Town Hill, which has 3 lanes with paved shoulders in each direction.
Condition of Road	Good.
Comments	Rehabilitation between Candella Road and Paradise Valley commenced in July 2013. Lane closures and reduced speeds will be signposted. The works will be undertaken at night between 18h00 and 05h00.
Duration of Work	July 2013 to March 2015.
Contact for Routine Road Maintenance	Lucille Mabena 083 537 3430 (Route Manager) 24hr number 074 583 3576 Jared Reddy 082 478 1165

National Route	N3 (The N3 Toll Route operated by N3 Toll Concession (Pty) Ltd)
Section	Cedara to Heidelberg
Distance	415 km
Description	This section of road is a public private partnership between SANRAL and the N3Toll Concession (Pty) Ltd. This toll route is a four-lane dual carriageway road between Cedara and the Tugela Toll Plaza. From the Tugela Toll Plaza to the Wilge Toll Plaza (Villiers) the road is a four-lane single carriageway with shoulders of varying width. The section between the Tugela Toll Plaza and Warden has at-grade intersections and access roads. The remainder of the road between Villiers and Heidelberg is a four-lane dual carriageway with paved shoulders.
Condition of Road	Good.

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

Comments	<p>Current planned construction works include:</p> <ul style="list-style-type: none"> <li>i) Rehabilitation between Mooi River and Estcourt commenced from October 2013 and is programmed for completion on 31 August 2015.</li> <li>ii) Rehabilitation between the Sand River and Keeversfontein commenced from October 2013 and is programmed for completion on 31 August 2015.</li> <li>iii) Rehabilitation between the De Hoek Plaza and Heidelberg commenced on 1 September 2013 and is programmed for completion on 31 May 2014.</li> <li>iv) Ongoing routine road maintenance, grass cutting and litter collection.</li> </ul> <p>Through the construction zones, traffic may be restricted to one lane in each direction under reduced speed. During the period 13 December 2013 to 7 January 2014, all four lanes will be open to traffic.</p> <p>Road users are urged to obey speed limits, maintain safe following distances and to refrain from littering. Please reduce speed and drive carefully in the proximity of fire break burning.</p>
Duration of Work	Please see above. Maintenance personnel will be on standby to deal with any emergency repairs.
Contact for Routine Road Maintenance	N3TC Customer Care Line 0800 634 357 0800 N3 HELP

National Route	N3
Section	Heidelberg to Johannesburg
Distance	50 km
Description	Four-lane dual carriage freeway.
Condition of Road	Good.
Comments	
Duration of Work	No construction
Contact for Routine Road Maintenance	Henk Diedericks 082 704 6553

National Route	N3 (GFIP)
Section	Heidelberg Weg Interchange to Geldenhuis Interchange
Distance	12 km
Description	Construction of six lanes and upgrade of Interchanges – Lane restriction in off peak hours
Comments	No construction
Duration of Work	

National Route	N3 (GFIP)
Section	Geldenhuis Interchange to Buccleuch Interchange
Distance	17,6 km
Description	Construction of six lanes and upgrade of Interchanges – Lane restriction in off peak hours
Comments	No Construction.
Duration of Work	

## N4

National Route	N4 ( Platinum Highway )
Section	Botswana Border to Zeerust
Distance	60 km
Description	Two-lane single carriageway with paved shoulders.
Condition of Road	Good.
Comments	No construction.
Duration of Work	
Contact for Routine Road Maintenance	Pt Ops 012 804 0044

National Route	N4 ( Platinum Toll Highway )
Section	Zeerust to Rustenburg
Distance	120 km
Description	Two-lane single carriageway with paved shoulders.
Condition of Road	Good.
Comments	No Construction.

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

Duration of Work	
Contact for Routine Road Maintenance	Pt Ops 012 804 0044

National Route	N4 (Platinum Toll Highway)
Section	Rustenburg to Brits (R512 Interchange)
Distance	70 km
Description	Two-lane single carriageway freeway.
Condition of Road	Good.
Comments	Motorists must be aware and be on the look out for pedestrians and animals in the Bapong area. Adhere to posted speed limits.
Duration of Work	
Contact for Routine Road Maintenance	Pt Ops 012 804 0044

National Route	N4 West Magalies Toll Road
Section	Rebecca Street to Pelindaba
Distance	21 km
Description	Mixture of two-lane dual carriageway and two-lane single carriageway freeway.
Condition of Road	Good.
Comments	No construction.
Duration of Work	
Contact for Routine Road Maintenance	Herman du Plessis 082 771 4886

National Route	N4
Section	Pretoria to Hans Strydom Interchange
Distance	13.6 km
Description	A 6-lane dual carriageway road up to Simon Vermooten Interchange, thereafter a 4-lane dual carriage way.
Condition of Road	Good.
Comments	No construction.
Duration of Work	
Contact for Routine Road Maintenance	Obed Monare 072 746 9267

National Route	N4
Section	Hans Strydom Interchange to Mozambique
Distance	304 km
Description	Four-lane dual carriageway from Hans Strydom Int. to Van Dyk's Drift. Thereafter, a four-lane undivided road to Wonderfontein, then 2 lanes undivided to the Mozambique border.
Condition of Road	Good.
Comments	No construction
Duration of Work	
Contact for Routine Road Maintenance	Trans African Concessionaires (TRAC) 013 755 3316

## N5

National Route	N5
Section	Harrismith to Bethlehem
Distance	88 km
Description	A two-lane single carriageway with wide paved shoulders. There are overtaking opportunities where severe grades occur.
Condition of Road	Fair to good.
Comments	Rehabilitation work has commenced between Harrismith and Kestell. Traffic accommodation by means of two way traffic can be expected. Temporary daytime Stop/Go's will be in place on occasions. Reduced speeds are signposted.
Duration of Work	Until April 2015 between Harrismith and Kestell
Contact for Routine Road Maintenance	Japie Taljaard

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

Maintenance	082 857 7175
-------------	--------------



National Route	N5
Section	Bethlehem to Winburg
Distance	120 km
Description	A two-lane single carriageway with varying width of either paved or gravel shoulders. There are overtaking opportunities where severe grades occur.
Condition of Road	Fair to good
Comments	<ol style="list-style-type: none"> <li>1. Maintenance crews will be active with occasional localised Stop/Go controls for asphalt patching work, between Bethlehem and Winburg.</li> <li>2. A rehabilitation contract between Vaalpensspruit and Winburg is in progress. Reduced speeds are signposted. Traffic is controlled by signalised Stop/Go controls.</li> </ol>
Duration of Work	<ol style="list-style-type: none"> <li>1. Maintenance crews are continuously active.</li> <li>2. Until January 2015.</li> </ol>
Contact for Routine Road Maintenance	Japie Taljaard 082 857 7175

## N6

National Route	N6
Section	East London to Stutterheim
Distance	70 km
Description	A two-lane single carriageway with paved shoulders and climbing lanes in places
Condition of Road	Fair to good
Contact for Routine Road Maintenance	Flip Jacobs 082 563 5218

National Route	N6
Section	Stutterheim to Cathcart
Distance	49 km
Description	A two-lane single carriageway with paved shoulders and climbing lanes in places
Condition of Road	Good.
Contact for Routine Road Maintenance	Flip Jacobs 082 563 5218

National Route	N6
Section	Cathcart to Queenstown
Distance	59 km
Description	A two-lane single carriageway with paved shoulders and climbing lanes in places.
Comments	Reseal project between Cathcart and Queenstown from Dec 2011 to Nov 2013
Condition of Road	Fair to Good
Contact for Routine Road Maintenance	Flip Jacobs 082 563 5218
Contact for Construction Project	Tobais de Haas 074 885 2249

National Route	N6
Section	Queenstown to Jamestown
Distance	107km
Description	A two lane single carriage way with paved shoulders
Condition of Road	Good
Comments	Regular to slow moving trucks with wind turbine components can be expected from Queenstown to beyond penhoek pass
Duration of Work	None
Contact for Routine Road Maintenance	Flip Jacobs 082 563 5218

National Route	N6
Section	Jamestown to Aliwal North
Distance	58 km
Description	A two-lane single carriageway with paved shoulders.
Condition of Road	Good
Contact for Routine Road Maintenance	Flip Jacobs 082 563 5218

National Route	N6
Section	Aliwal North to Bloemfontein
Distance	200 km
Description	Predominantly, a two-lane single carriageway with only the last 2.36km of National Route 6 having wide paved shoulders. The rest of the route has gravel shoulders of varying widths.
Condition of Road	The road between Paryshoogte and Bloemfontein is in a good condition. Between Aliwal North and Smithfield the road is in a good condition with some pavement repair teams working ad hoc. The rest of the route is satisfactory – except for the section between Smithfield and Paryshoogte which is currently being rehabilitated.
Comments	<ol style="list-style-type: none"> <li>1. A contract for the rehabilitation of the 34km long section between Smithfield and Paryshoogte (including the road through Smithfield) is in progress. A signalised Stop/Go control system is in place.</li> <li>2. A contract for the rehabilitation and resurfacing between Onze Rust and Bloemfontein will commence in January 2014, 2-way traffic will be accommodated on a widened cross-section.</li> </ol>
Duration of Work	Until April 2015.
Contact for Routine Road Maintenance	M A Majorobela 079 896 3377

## N7

National Route	N7
Section	Melkbos Turn-off to Clanwilliam
Distance	198 km
Description	A single carriageway road with paved shoulders between Melkbos and Piekienerskloof Pass; thereafter gravel shoulders.
Condition of Road	Fair to Good.
Comments	<p>A bypass has been constructed at Melkbosstrand intersection. Temporary stop/go control to allow construction vehicles to cross or join traffic, with minimal delay. Motorists to please reduce speed and proceed with caution.</p> <p>Construction works between Citrusdal And Cederberg:</p> <p>Construction works, affecting the travelling public, are in progress in the first 23km of the project (from the Citrusdal side). Motorists will encounter one, manually and traffic-light controlled, day and night Stop/Go section with a waiting period on average of 10 minutes. Other shorter temporary stop/go closures may be encountered with a shorter waiting time. The road may be closed for blasting on Mondays to Thursdays, between 15:00 and 16:00. Blasting times are displayed on signs at strategic intersections a week in advance. The speed limit throughout the construction area has been lowered, to either 80 km/h or 60km/h as indicated.</p> <p>Construction work is in progress between Cederberg T-Junction and the Paleisheuwel Junction.</p> <p>During November 2013, as during October 2013, motorists will encounter two day-night Stop/Go closures for half-width road reconstruction, from km 102.66 to km 106.6, and km 109.6 to km 113.6.</p> <p>Blasting has not been scheduled as yet, but the road may be closed if and when it is needed, in order for safe blasting to take place. Prior notice will however be given via road signs and local radio stations.</p> <p>Waiting time: 10-15 minutes at each closure.</p>
Duration of Work	Anticipated completion 07 February 2016

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

Contact for Routine Road Maintenance	Sandla Tsengiwe 083 701 4979
--------------------------------------	---------------------------------

National Route	N7
Section	Clanwilliam to Garies
Distance	63.4 km
Description	Single carriageway without paved shoulders
Condition of Road	Average
Comments	<p>Construction work is in progress between Trawal and Vanrhynsdorp turn off. During November 2013 motorists will encounter three day and night Stop/Go closures for construction purposes.</p> <p>Waiting time: 10-15 minutes at each closure.</p> <p>Construction Between Vanrhynsdorp to Bitterfontein: Construction works are resumed this month (September) and there are two closures on site between Vanrhynsdorp and Bitterfontein involving seal works and motorists are expected to encounter two closures with 10 minutes waiting period at each closure.</p> <p>Construction between Bitterfontein to Garies: Construction works are in progress over the full section of the project. Motorists will encounter five manually controlled Stop/Go sections with a waiting period on average of 10 minutes. Some of the Stop/Go sections will be in operation during night times..</p>
Duration of work	April 2013 until May 2014
Contact for Routine Road Maintenance	Louis Burger (Western Cape Section) -Etienne Wentzel (northern Cape Section) 074 1932 978 / 083 5147 090

National Route	N7
Section	Northern Cape Border to Vioolsdrift
Distance	412 km
Description	A single carriageway road with gravel shoulders.
Condition of Road	Good.
Comments	Routine road maintenance teams may be encountered. Motorists should also be alert to pedestrians and/or stray animals in the vicinity of Okiep and Steinkopf.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Chris Roux 083 440 7553
National Route	N7
Section	Steinkopf (km 47.0) to Vioolsdrift Border Post (km 115.8)
Distance	68.8
Description	Single carriageway with gravel shoulders and no climbing lanes. Rest areas at regular intervals
Condition of road	Fair
Comments	Motorists will encounter up to four day and night Stop/Go closures; manually controlled during the day and traffic signal units and flagmen at night as well as one daylight closures. Waiting period of $\pm 10$ min per closure.
Duration of Work	March 2013 to May 2014
Contact for Routine Road Maintenance	Ettienne Wentzel 083 514 7090

## N8

National Route	N8
Section	Groblershoop to Kimberley
Distance	285 km
Description	Single carriageway with paved shoulders. Stopping places are provided at regular intervals.
Condition of Road	Fair.
Comments	<p>Construction works are in progress between Groblershoop and Kimberly.</p> <p>Between Groblershoop and Volop (91km) there are no closures as construction is complete</p> <p>Motorists will encounter up to four manually controlled Stop/Go closures during the daytime and three traffic signal units at night. Waiting periods up to 10 minutes at each can be expected during daytime.</p>

	Please be attent to the warning signals of flagmen along the route. Some sections of the road are newly sealed and do not yet have line markings.  Motorists should be alert to stray animals such as donkeys and goats. The route is prone to Kudu buck in the roadway between dusk and dawn
Duration of Work	Until November 2013
Contact for Routine Road Maintenance	Pule Khomamatoli 082 753 0359

National Route	N8
Section	Kimberley to Bloemfontein
Distance	150 km
Description	Predominantly, a two-lane single carriageway. The 29 km section between Kimberley and Perdeberg has paved shoulders, while the final eight km immediately adjacent to Bloemfontein is a four – lane dual carriageway with wide paved shoulders. The remainder of the road has gravel shoulders.
Condition of Road	Fair
Comments	<ol style="list-style-type: none"> <li>1. Rehabilitation work on the section between Alexanderfontein and Petrusburg (49.5 kms) is in progress. No stop/go controls currently in place, but reduced lane widths and speed limits are in operation.</li> <li>2. Rehabilitation work on the section between De Brug and Kloofeind (31.5 kms) is in progress. No Stop/Go controls in place, but shoulder closures can be expected.</li> <li>3. Rehabilitation work on the section between Kloofeind to Haldon interchange (N8/N1) will commence in April 2014</li> </ol>
Duration of Work	<ol style="list-style-type: none"> <li>1. Alexanderfontein – Petrusburg until February 2014.</li> <li>2. De Brug – Kloofeind until November 2013.</li> <li>3. Kloofeind – Haldon until December 2015</li> </ol>
Contact for Routine Road Maintenance	Riaan Louwrens 074 601 8998

National Route	N8
Section	Bloemfontein to Maseru
Distance	135 Km
Description	The first five km section from Bloemfontein is a four-lane dual carriageway with wide paved shoulders. Between Bloemfontein and Thaba Nchu there are alternating passing and climbing lanes. Between Thaba Nchu and Ladybrand is a two-lane single carriageway road with shoulders of varying widths. Route 26/N8-13 (km 0.0) to Maseru Border (km 11.75) is in good condition.
Condition of Road	Good
Comments	Construction of the Thaba Nchu Interchange is in progress with speed and height restrictions in place. Motorists are urged to obey the posted speed limits.
Duration of Work	Completion date for Thaba Nchu Interchange is March 2014.
Contact for Routine Road Maintenance	M A Majorobela 079 896 3377

## N9

National Route	N9
Section	Western Cape and Eastern Cape Boundary to Aberdeen
Distance	138 km
Description	A two-lane single carriageway with gravel shoulders.
Condition of Road	Good
Comments	No construction but motorists may encounter occasional short-term closures over short sections for routine maintenance.
Contact for Routine Road Maintenance	Christo Muller 083 628 0272

National Route	N9
Section	Aberdeen to Graaff Reinet
Distance	54 km
Description	A two-lane single carriageway with paved shoulders.
Condition of Road	Good.
Comments	No construction but motorists may encounter occasional short-term closures over short sections for routine maintenance.
Duration of Work	
Contact for Routine Road Maintenance	Christo Muller 083 628 0272

National Route	N9
Section	Graaff-Reinet to Middelburg
Distance	105 km
Description	A Two-Lane single carriageway with paved shoulders
Condition of Road	Good.
Comments	In Loodsberg pass, construction work to repair. Rockfalls is in progress. No Stop-Go's will be encountered
Contact for construction work	Christo Muller 083 628 0272

National Route	N9
Section	Middelburg to the intersection of the N10 and N9 between Middelburg and Noupoot (Carlton Heights)
Distance	24 km
Description	Single carriageway with short section of paved shoulders.
Condition of Road	Fair to Poor
Comments	No construction but motorists may encounter occasional short-term closures over short sections for routine maintenance.
Contact for Routine Road Maintenance	Christo Muller 083 628 0272

National Route	N9
Section	Colesberg to Carlton Heights
Distance	70 km
Description	Single carriageway with paved shoulders and climbing lanes. Rest areas at regular intervals.
Condition of Road	Fair
Comments	Construction works are in progress between Colesberg and Wolwefontein  Between and Carlton Heights Wolwefontein: Construction on this section is complete.  Between Wolwefontein and Colesberg: Motorists can expect TWO manually controlled Stop/Go sections during the day and traffic signal units at night with waiting periods on average 10 minutes.
Duration of Work	March 2011 to March 2014
Contact for Routine Road Maintenance	Dan Louw 083 383 8174

## N10

National Route	N10
Section	Paterson – Olifantskop Pass
Distance	23 km
Description	Two lane single carriageway road. Some passing lanes in pass
Condition of Road	Good
Duration of work	
Comments	Regular slow moving trucks with wind turbine components can be expected between 09h00 and in the Olifantskopass maybe subject to 30 minutes closure for those loads
Contact for Routine Road Maintenance	Marko du Plessis 079 893 6256

National Route	N10
Section	Olifanskop Pass to Baviaans River north of Cookhouse
Distance	134 km
Description	This section is a two-lane single carriageway road with wide surfaces shoulders.
Condition of Road	Good
Comments	

National Route	N10
Section	Riet River to Cradock
Distance	37 km
Description	Two-lane single carriageway with narrow paved shoulders. The N10 Between Cookhouse and Cradock may I be closed on Tuesdays and Thursdays between 12:00 and 16:00, due to blasting.
Condition of Road	Fair/Poor.
Comments	The road may be closed for blasting on Tuesdays and Thursdays from 12H0-16h00
Contact for Routine Road Maintenance	Marko du Plessis 079 893 6256

National Route	N10
Section	Baviaans River to Riet River
Distance	25 km
Description	Two-lane single carriageway with narrow gravel shoulders.
Condition of Road	Fair/Poor.
Comments	The upgrade contract for this section of the road has started. Stop-Go may be encountered and speed restrictions through the construction works will be in place.
Duration of work	27 Months (March 2015)
Contact for Routine Road Maintenance	Marko du Plessis 079 893 6256
Contact for Construction	Johan Knoesen 082 417 4778

National Route	N10
Section	Cradock to Middelburg
Distance	95 km
Description	The first 43 km is a two-lane single carriageway road with wide paved shoulders. The last 30 km is a two-lane single carriageway road with narrow gravel shoulders
Condition of Road	Fair Cradock to Express Grove
Comments	
Contact for Routine Road Maintenance	Marko du Plessis 079 893 6256- Andrew Ssekayita is the contact for construction : 071 572 4709

National Route	N10
Section	Ludlow (Intersection of the N10 and N9 between Middelburg and Noupoort) to Hanover
Distance	62 km
Description	Single carriageway with paved shoulders, thereafter gravel shoulders.
Condition of Road	Good
Comments	Routine road maintenance teams may be encountered.
Duration of Work	Complete
Contact for Routine Road Maintenance	Roland Siebrits 073 424 9767

National Route	N10
Section	Danverton to Britstown
Distance	44 km
Description	Single carriageway with narrow paved shoulders.
Condition of Road	Fair to Good
Comments	Routine Road Maintenance teams may be encountered.
Duration of work	Ongoing.
Contact for Routine Road Maintenance	Roland Siebrits 073 424 9767

National Route	N10
Section	Britstown to Prieska
Distance	126 km
Description	Single carriageway with gravel shoulders.
Condition of Road	Good
Comments	Construction work West of Britstown is complete. Routine road maintenance teams may be encountered.
Duration of Work	Construction complete. Ongoing routine road maintenance.
Contact for Routine Road Maintenance	Roland Siebrits 073 424 9767

National Route	N10
Section	Prieska to Groblershoop
Distance	129 km
Description	Single carriageway with gravel shoulders.
Condition of Road	Good
Comments	Construction works between Prieska and Groblershoop is complete.  Between Marydale and Groblershoop (56km): No further closures expected. Drivers should, however, be aware that clean up of the site and road marking is underway.
Duration of Work	July 2011 until June 2012
Contact for Routine Road Maintenance	Charles van Wyk 076 281 1433

National Route	N10
Section	Groblershoop to Upington
Distance	116 km
Description	Single carriageway with gravel shoulders. Road widening through winelands of Orange River Valley with sharp curves and steep gradients.
Condition of Road	Fair to good.
Comments	September 2012 – August 2013  Four stop/go closures at bridges waiting time 5 min. operating day only when pouring concrete. Motorists should also be alert to pedestrians and/ or stray animals in the road reserve..
Duration of Work	July 2011 until Aug 2013
Contact for Routine Road Maintenance	Charles van Wyk 076 281 1433

National Route	N10
Section	Upington to Nakop (Namibian Border)
Distance	134 km
Description	Single carriageway road with gravel shoulders.
Condition of Road	Good.
Comments	Construction work is complete on N10/12 west of Upington for 60 Km.  From 1 August 2013 the road will be open to traffic.
Duration of Work	July 2012 to July 2013
Contact for Routine Road Maintenance	Charles van Wyk 076 281 1433



## N11

National Route	N11
Section	N3 Bergville Interchange to Newcastle
Distance	115 km
Description	A two-lane single carriageway with narrow shoulders, except for the 16 km portion before Newcastle and for short sections through the Biggarsberg Mountain range, where there are passing lanes.
Condition of Road	Variable, generally good.
Comments	1. The rehabilitation is complete, with minor works being completed. 2. Rehabilitation work on the section between Nkunzi River and the R68 intersection to Dundee is in progress with traffic calming measures in place. No Stop/Go controls are in place.
Duration of Work	1. The minor works for the rehabilitation from Bergville/N3 Interchange to Ladysmith project are expected to be completed during November 2013. 2. Rehabilitation between Nkunzi River to N11-3/R68 intersection until July 2014. 3. Maintenance work is ongoing.
Contact for Routine Road Maintenance	Ridwaan Ghany 031 262 6950 / 083 550 0622

National Route	N11
Section	Newcastle to Volksrust
Distance	54 km
Description	Apart from the 9 km that constitute the Newcastle Bypass and the 17 km that make up the Laingsnek (Majuba) Mountain Pass, the road is a single carriageway, with narrow paved shoulders.
Condition of Road	Fair to good
Comments	
Duration of Work	
Contact for Routine Road Maintenance	Ridwaan Ghany 031 262 6950 / 083 550 0622

National Route	N11
Section	Volksrust to Amersfoort
Distance	50 km
Description	A two-lane single carriageway with narrow gravel shoulders. The whole section is heavily trafficked.
Condition of Road	Good
Comments	No Construction
Duration of Work	
Contact for Routine Road Maintenance	Kobus Vermeulen 082 3046566

National Route	N11
Section	Amersfoort to Ermelo
Distance	51 km
Description	A two-lane single carriageway road with narrow gravel shoulders.
Condition of Road	Poor.
Comments	
Duration of Work	No Construction.
Contact for Routine Road Maintenance	Kobus Vermeulen 082 304 6566

National Route	N11
Section	Ermelo to Middelburg
Distance	101 km
Description	A two-lane single carriageway with wide gravel shoulders.
Condition of Road	Good.
Comments	No construction.
Duration of Work	
Contact for Routine Road Maintenance	Kobus Vermeulen 082 304 6566

National Route	N11
Section	Middelburg to Groblersdal
Distance	82 km

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

Description	A two-lane single carriageway with narrow gravel shoulders.
Condition of Road	Good
Comments	Construction at Loskopdam started
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Obed Monare 072 7469267

National Route	N11
Section	Groblersdal via Marblehall to Old Mpumalanga / Limpopo Border
Distance	38 km
Description	A two-lane single carriageway road with narrow gravel shoulders.
Condition of Road	Good
Comments	Mpumalanga Border towards R101 Construction started
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Obed Monare 072 7469267

National Route	N11
Section	Old Mpumalanga Border (North of Marble Hall) – Mokopane (Potgietersrust) – Groblersdrift Border Post
Distance	276 km
Description	Two-lane single carriageway.
Condition of the road	Good
Comments	No Construction
Duration of work	
Contact for Routine Road Maintenance	Stephan du Plessis 084491 1165

## N12

National Route	N12
Section	Three Sisters to Victoria-West
Distance	61 km
Description	Single carriageway with paved shoulders.
Condition of Road	Good.
Comments	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Morne Lamprecht 083 674 7735

National Route	N12
Section	Victoria-West to Britstown
Distance	104 km
Description	Single carriageway with paved shoulders.
Condition of Road	Good.
Comments	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing.
Contact for Routine Road Maintenance	Morne Lamprecht 083 674 7735

National Route	N12
Section	Britstown to Hopetown
Distance	134 km
Description	Single carriageway with narrow paved shoulders.
Condition of Road	Good.
Comments	Construction between Britstown and Strydenburg is complete.  Construction between Strydenburg and Hopetown is complete.
Duration of Work	May 2011 – November 2013.
Contact for Routine Road Maintenance	Morne Lamprecht 083 674 7735

National Route	N12
----------------	-----

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

Section	Hopetown to Kimberley
Distance	118 km
Description	Single carriageway with paved shoulders.
Condition of Road	Good.
Comments	Routine Road Maintenance teams may be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Milton van Heerden 083-362-9707

National Route	N12
Section	Kimberley to Northern Cape Border
Distance	85 km
Description	Single carriageway with paved shoulders.
Condition of Road	Good.
Comments	Routine Road Maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Milton van Heerden 083-362-9707

National Route	N12
Section	North West / Northern Cape Border at Warrenton to Christiana
Distance	42 km
Description	Two-lane single carriageway with unpaved shoulders.
Condition of Road	Good
Comments	Repairs are being done to the bridge across the Vaal river. Motorists can expect one shoulder closure on the bridge, without Stop/Go controls and, thus, no waiting period. No shoulder closure over Easter weekend.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Nico du Toit 079 8960201

National Route	N12
Section	Christiana to Bloemhof
Distance	52 km
Description	Two-lane narrow single carriageway with unpaved shoulders.
Condition of Road	Good
Comments	
Duration of Work	Rehabilitation Completed.
Contact for Routine Road Maintenance	Nico du Toit 079 8960201

National Route	N12
Section	Bloemhof to Wolmaranstad
Distance	64 km
Description	Two-lane narrow single carriageway with unpaved shoulders.
Condition of Road	Good
Comments	
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Nico du Toit 079 8960201

National Route	N12
Section	Welnsdorp to Kerkdorp
Distance	25 km
Description	Two-lane single-carriage carriageway with unpaved shoulders most of the section, except closer to Kerkdorp.
Condition of Road	Good
Condition of Road	Good to very good.
Current Work	No Construction
Duration of Routine Road Maintenance	Nico du Toit 079 8960201
Contact for Routine Road Maintenance	Nico du Toit 079 8960201
Maintenance	

National Route	N12
Section	Potchefstroom to North West Border at Carltonville
Distance	51 km
Description	Two-lane narrow single carriageway with passing lanes.
Condition of Road	Fair.
Comments	No construction
Duration of Work	
Contact for Routine Road Maintenance	Nico du Toit 079 8960201

National Route	N12
Section	Diepkloof Interchange to Gauteng/Mpumalanga Border
Distance	50km
Description	Four-lane dual carriageway freeway.
Condition of Road	Fair to Good.
Comments	
Duration of Work	
Contact for Routine Road Maintenance	Henk Diedericks 082 704 6553

National Route	N12 (GFIP)
Section	Reading to Elands Interchange
Distance	4 km
Description	
Comments	No Construction
Duration of Work	

National Route	N12
Section	Gauteng / Mpumalanga Border to eMalahleni
Distance	115 km
Description	Four-lane dual carriageway freeway
Condition of Road	Good to fair
Comments	Rehabilitation in progress
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Obed Monare 072 746 9267

National Route	N12
Section	Gillooly's Interchange & R21 Interchange
Distance	
Description	
Condition of Road	
Comments	Construction in progress
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Willem van der Merwe 083 283 6073

National Route	N12
Section	R21 & Tom Jones
Distance	
Description	
Condition of Road	
Comments	Construction in progress
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Willem van der Merwe 083 283 6073

National Route	N12
Section	Tom Jones & Daveyton Interchanges
Distance	
Description	
Condition of Road	
Comments	Construction in progress
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Willem van der Merwe 083 283 6073

National Route	N12
Section	Misgund Interchange and Golden Highway
Distance	
Description	
Condition of Road	
Comments	Construction in progress at Intrchanges
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Manie du Plessis 082 3071678

## N14

National Route	N14
Section	Springbok to Pofadder
Distance	163 km
Description	Single carriageway with paved shoulders.
Condition of Road	Good.
Comments	Construction work is in progress between Springbok and Witputs, and between Witputs and Pofadder. Springbok to Witputs: Construction works between Springbok and Witputs is complete.  Witputs to Pofadder (expected completion June 2013): Construction works between Witputs and Pofadder is complete  Routine Road Maintenance teams may be encountered.
Duration of Work	August 2012 until June 2013
Contact for Routine Road Maintenance	Bernice Cloete 082-304 6553

National Route	N14
Section	Pofadder to Kakamas
Distance	130 km
Description	Single carriageway with paved shoulders.
Condition of Road	Good
Comments	Construction work between Pofadder and Bladgrond and between Bladgrond and Kakamas.  Pofadder to Bladgrond: Construction is complete.  Bladgrond to Kakamas: Construction is complete.  Road marking teams are on site and motorists should be alert to them.
Duration of Work	August 2012 until June 2013
Contact for Routine Road Maintenance	Bernice Cloete 082-304 6553

National Route	N14
Section	Kakamas to Keimoes
Distance	41km
Description	Single carriageway with gravel shoulders.
Condition of Road	Good.
Comments	<p>Re-construction and repair work is complete. The seal work and bridge works were both completed 26 October 2013, and the outstanding work consists of the final installation of the joints at each of the four bridges, which commences 26 October 2013, and line painting and installation of the reflective road studs.</p> <p>Both the line painting and the road studs have been ongoing already and have been completed to within ten kilometres of Kakamas. Continued work will require the use of flag people to alert motorists, but no delays will be caused to motorists by this work.</p> <p>The bridge joint work will require the use of a day closure to control traffic in the immediate vicinity of each bridge in turn. Any delay caused to motorists will be of very short duration, of the order of two minutes at the most. This is not expected to continue beyond the middle of November 2103</p>
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Bernice Cloete 082-304 6553

National Route	N14
Section	Keimoes to Upington
Distance	35 km
Description	Single carriageway with paved shoulders.
Condition of Road	Good.
Comments	<p>Bridge construction is taking place at SIX sites between Keimoes in the direction of Upington (for 30km) (May 2012 – May 2013). Road narrowing at these sites can be expected; Stop/Go with manually controlled closures during the day time with short delays of approximately 10 minutes.</p> <p>Routine road maintenance teams may be encountered.</p> <p>Construction work on road surface between Keimoes and Upington (Aug 2012 – Apr 2013): Construction is complete.</p>
Duration of Work	May 2012 to May 2013
Contact for Routine Road Maintenance	R Louwrens 083 406 6371

National Route	N14
Section	Upington to Olifantshoek
Distance	166 km
Description	Single carriageway with short section of paved shoulders.
Condition of Road	Good.
Comments	<p>Construction works are in progress between Upington and Boplaas. Motorists may encounter one Stop/Go traffic closure during the day with traffic signal units at night; approximate waiting periods of 10 minutes per closure.</p> <p>Construction work will be completed by 14 December 2012 and no further closures are expected.</p> <p>Routine road maintenance teams may be encountered.</p>
Duration of Work	July 2010 until December 2012.
Contact for Routine Road Maintenance	Riaan Louwrens 083 406 6371

National Route	N14
Section	Olifantshoek to Kuruman
Distance	97 km
Description	Single carriageway with gravel shoulders.
Condition of Road	Good.
Comments	Construction works are in progress between Olifantshoek and Kathu and between Kathu and Kuruman.

*Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered*

	Olifantshoek to Kathu: Construction work is now complete on this section. Kathu to Kuruman: Construction on this section is complete and no further closures are expected.
Duration of Work	July 2010 until October 2013
Contact for Routine Road Maintenance	Riaan Lourens 083 406 6371

National Route	N14 (Northern Cape)
Section	Kuruman to Vryburg
Distance	0-52 km
Description	Single narrow carriageway with gravel shoulders.
Condition of Road	Good/Fair
Comments:	Motorists may expect 4 day and night Stop/Go closures. Waiting time approximately 15 minutes at each closure. 790% of the BSM is complete and 75% of the road surfacing is complete.
Duration of Work	June 2012 until October 2013
Contact for Routine Road Maintenance	Riaan Lourens 083 406 6371

National Route	N14 Section 8 (Northern Region)
Section	Kuruman to Vryburg
Distance	52-142 km
Description	
Condition of the road	Good
Comments	Reseal work started in January 2012.
Duration of work	Ongoing
Contact for Routine Road Maintenance	

National Route	N14
Section	Vryburg to Delareyville
Distance	82 km
Description	Single carriageway with gravel shoulders.
Condition of Road	Fair to poor.
Comments	Construction works in progress. Stop / Go controls may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Nico Bosman 082 444 8858

National Route	N14
Section	Delareyville to Coligny
Distance	104 km
Description	Single carriageway with gravel shoulders.
Condition of Road	Fair to poor.
Comments	Construction works in progress. Stop / Go controls may be encountered.
Duration of Work	Construction started in January 2012.
Contact for Routine Road Maintenance	Nico Bosman 082 444 8858

National Route	N14
Section	Coligny to Ventersdorp
Distance	53 km
Description	Single carriageway with gravel shoulders.
Condition of Road	Fair.
Comments	Patching work started in January 2012.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Nico Bosman 082 444 8858

National Route	N14
Section	Ventersdorp to North West / Gauteng Border
Distance	101 km

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered



Description	Single carriageway with gravel shoulders.
Condition of Road	Poor and uneven in places. Bypass in operation at sinkhole close to Gauteng provincial boundary
Comments	Construction started in January 2012.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Nico Bosman 082 444 8858

National Route	N14 Section 13
Section	Ventersdorp to North West / Gauteng Province Border
Distance	
Description	
Condition of the road	
Comments	
Duration of work	Construction resumed in January 2012
Contact for Routine Road Maintenance	

## N17

National Route	N17
Section	Soweto to Nasrec
Distance	6 km
Description	New alignment
Condition of Road	Good
Comments	No Construction
Duration of Work	
Contact for Routine Road Maintenance	Marthinus Wilken 082 7821746

National Route	N17
Section	Johannesburg to Springs
Distance	35 km
Description	A 4-lane dual carriageway.
Condition of Road	Good.
Comments	No construction.
Duration of Work	
Contact for Routine Road Maintenance	Manie du Plessis 082 3071678

National Route	N17
Section	Springs to Leandra
Distance	53 km
Description	Single carriageway with paved shoulders in places.
Condition of Road	Fair.
Comments	No Construction
Duration of Work	
Contact for Routine Road Maintenance	Kobus Vermeulen 082 304 6566

National Route	N17
Section	Davel to Ermelo
Distance	
Description	
Condition of the road	
Comments	Upgrade – At least two Stop/Go for 4km long & 20 minute delay at each.
Duration of work	Construction will resume January 2012
Contact for Routine Road Maintenance	Jan Gerber 082 551 1975

National Route	N17
Section	Bloemhof to Rietpan

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

Distance	
Description	
Condition of the road	
Comments	Construction work resume in January 2012.
Duration of work	Ongoing
Contact for Routine Road Maintenance	Tieker vd Berg 082 413 3479

National Route	N17
Section	Leandra to Kinross
Distance	15Km
Description	New Alignment
Condition of Road	
Comments	Construction work resume in January 2012.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	H du Preez 083 235 0141

National Route	N17
Section	Kinross via Bethal to Ermelo
Distance	99 km
Description	Single carriageway with gravel shoulders.
Condition of Road	Fair to Poor, uneven in places.
Comments	There is rehabilitation between Trichardt & Bethal.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Kobus Vermeulen 082 304 6566

National Route	N17
Section	Ermelo to Oshoek Border Post
Distance	122.59 km
Description	Single carriageway with paved shoulders.
Condition of Road	Fair to poor
Comments	Construction between Ermelo and Chrissiesmeer
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Gustav Fouche: 0827802391

National Route	N17
Section	Rossetenville to Wits Rifle Road
Distance	
Description	
Condition of the road	
Comments	Overlay / Construction started
Duration of work	Ongoing
Contact for Routine Road Maintenance	Hendrik Amego 082 307 8106

## **N18 (R49)**

National Route	N 18 (R49)
Section	Warrenton to Hartswater (Northern Cape Border)
Distance	55 km
Description	Single carriageway with paved shoulders.
Condition of Road	Good.

Comments	A maximum of four STOP/GO's will be operating during November 2013. These are for base stabilization and seal work and will be day and night. Delays of about 20 minutes may be experienced at each closure. A rolling closure will be in operation for two weeks to accommodate rut filling on the road surface.  The road surface is in a good condition and temporary white lines have been painted to improve traffic safety especially during the night.
Duration of Work	
Contact for Routine Road Maintenance	Milton van Heerden 083-362-9707

National Route	N 18
Section	Northern Cape / North West Border at Taung to Vryburg
Distance	119 km
Description	Single carriageway with gravel shoulders.
Condition of Road	Good.
Comments	No construction
Duration of Work	
Contact for Routine Road Maintenance	Sarel Oberholzer 083-417-7546

National Route	N18
Section	Northern Cape / North West Border to Mafikeng
Distance	76 km
Description	Seal Teams may be encountered. Stop/Go may be encountered with 10 minute delays Insitu Recycling on Asphalt Works
Comments	Construction started
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Frank Joubert 083 781 3676

National Route	N18
Section	Vryburg to Mafikeng
Distance	151 km
Description	Single carriageway with gravel shoulders.
Condition of Road	Good.
Comments	No construction
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Frank Joubert 083 781 3676

## OTHER NATIONAL ROUTES

National Route	R22
Section	Hluhluwe to Farazela (RSA/Mozambique border)
Distance	175 km
Description	A 2-lane single carriageway road with narrow paved shoulders throughout.
Condition of Road	Good
Comments	
Duration of Work	
Contact for Routine Road Maintenance	Gonie Govender 084 466 2198

National Route	P720
Section	N2 to Golela Border Post with Swaziland
Distance	10 km
Description	A Single carriageway road between National Route 2 and Golela Border Post. Two lanes and a narrow paved shoulder and wide gravel shoulder in each direction.
Condition of Road	Good.
Comments	
Duration of work	

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

Contact for Routine Road Maintenance	Gonie Govender 084 466 2198
--------------------------------------	--------------------------------

  

National Route	R23
Section	Heidelberg to Standerton
Distance	93km
Description	Single carriageway road with paved shoulders.
Condition of Road	Variable but generally fair with rutting is some sections. Care must be taken when it rains
Comments	Construction to start in July 2012
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Phillip Fourie 083 410 2601

  

National Route	R23
Section	Standerton to Volksrust
Distance	80 km
Description	Single carriageway road with unpaved shoulders.
Condition of Road	Fair to good. Fair with a lot of rutting.
Comments	No construction
Duration of Work	
Contact for Routine Road Maintenance	Phillip Fourie 083 410 2601

  

National Route	R23
Section	Platrand
Distance	
Description	
Condition of Road	Fair
Comments	Stop/Go will be encountered
Duration of Work	Ongoing
Contact for Routine Road Maintenance	

  

National Route	R21
Section	N1 to N12
Distance	30 km
Description	Dual carriageway.
Condition of Road	Very Good
Comments	
Duration of Work	No construction
Contact for Routine Road Maintenance	Henk Diederiks 082 704 6553

  

National Route	R27
Section	Vanrhyns Pass to Calvinia
Distance	82 km
Description	Single carriageway road with gravel shoulders.
Condition of Road	Good.
Comments	<p>Construction work is in progress between the WC/NC border and Calvinia.</p> <p>During October 2013 motorists will encounter four day and night manually and traffic signal controlled Stop/Go closures for half-width road reconstruction. Some of the closures may move to different locations during the month. Waiting time 10-15 minutes.</p> <p>Nine sections of 4km each will have been reconstructed and opened to traffic. On these sections there will be no line markings or limited temporary line markings at no-overtaking sections.</p> <p>Temporary red road studs will have been installed over the full length of these sections.</p>
Duration of Work	July 2012 until September 2014
Contact for Routine Road Maintenance	Jacques Wentzel 079 514 3496

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

National Route	R27
Section	Calvinia to Brandvlei
Distance	147 km
Description	Single carriageway road with gravel shoulders.
Condition of Road	Good.
Comments	<p>Between Calvinia and Brandvlei  <u>Report for period 1 October to 31 October 2013</u></p> <ul style="list-style-type: none"> <li>▪ Between Calvinia and Brandvlei Intersection km 0 to km 21 :-</li> <li>▪ No closures to be erected as all roadworks are complete. Only finishing of road reserve to be done.</li> <li>▪ On Brandvlei Section km 21 to km 74 :-</li> <li>▪ 1 x 12 hour Day only Moving Closure of any one lane km 35-74 for finish / repair work as required.</li> </ul> <p>Construction in progress between Km73.0 and Brandvlei:  Shoulder widening and half width construction is currently in progress between km 80,200 and km 119.613. Four stop / go closures are in operation 24 hours. Delays up to 10 minute per closure may be encountered.</p> <p>Between Km 80.200 and Km 119,615 texture slurry is in progress and a day closure will be present on this section of road. This closure length will not exceed 4 kilometres per day.</p> <p>The speed restriction is 60km/h in the construction closures.</p> <p>Periodic road maintenance teams may be encountered.</p>
Duration of Work	September 2011 until February 2014
Contact for Routine Road Maintenance	Jacques Wentzel 079 514 3496

National Route	R27
Section	Brandvlei to Kenhardt
Distance	141 km
Description	Single carriageway road with gravel shoulders.
Condition of Road	Good.
Comments	Routine road maintenance teams may be encountered.
Duration of Work	Ongoing
Contact for Routine Road Maintenance	Johannes Rakwena 082 304 6880

National Route	R27
Section	Kenhardt to Keimoes
Distance	76 km
Description	Single carriageway road with gravel shoulders.
Condition of Road	Good.
Comments	<p>Bridge construction is taking place for 5km from Keimoes in the direction of Kenhardt.  During the period 1 Aug 2013 to 16 Aug 2013 a road closure of 1.5km within the 5km road construction section will be in operation. The closure will be regulated by means of stop/go signs and traffic signals during the day and night respectively. An expected delay of at least 10 minutes can be expected.  Routine road maintenance teams may be encountered.  Road construction works in progress between Kehardt and Keimoes:</p> <p>Report for period 1 October 2013 to 31 October 2013:</p> <ul style="list-style-type: none"> <li>▪ 1 x 24hr Day/Night Closure of one lane Km 22 to Km 26.</li> <li>▪ 1 x 24hr Day/Night Closure of one lane Km 14 to Km 18.</li> <li>▪ 1 x 24hr Day/Night Closure of one Lane Km 6 to Km 10.</li> <li>▪ 2x 12hr Day Moving Closure of one lane RHS &amp; LHS - Km 0 to Km 75 (Crack seal &amp; slurry).</li> </ul>
Duration of Work	January 2011 – April 2014
Contact for Routine Road Maintenance	Johannes Rakwena 082 304 6880

National Route	S27
Section	Villiers to Heidelberg
Distance	62 km

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

Description	Single carriageway with gravel shoulders and short gravel road portion.
Condition of Road	Good (Gravel road in bad condition).
Comments	No construction.
Duration of Work	
Contact for Routine Road Maintenance	Phillip Fourie 083 410 2601

National Route	R30/R730/R34 Toll Road	
Section	Bloemfontein to Kroonstad via Brandfort/Welkom	
Distance	210 km	
Description	A single carriageway between National Route N1 and Virginia. It accommodates two lanes and has wide paved shoulders and ad hoc climbing lanes in each direction. The section between Virginia and Welkom is a double carriageway and the section between Welkom and Kroonstad is a four-lane undivided carriageway with paved shoulders.	
Condition of Road	Good.	
Comments	No construction	
Duration of work		
Contact for Routine Road Maintenance	Japie Taljaard 082 857 7175	Attie Badenhorst 082 789 3533

National Route	R33
Section	From KwaZulu-Natal border, over Piet Retief up to N17 near Warburton
Distance	139 km
Description	Single carriageway with gravel shoulders.
Condition of the road	Fair but uneven in places.
Comments	No construction.
Duration of work	
Contact for Routine Road Maintenance	Wim Prinsloo 082 494 8947

National Route	R33
Section	From N17 near Warburton, over Carolina up to N4 near Belfast
Distance	89 km
Description	Single carriageway with gravel shoulders.
Condition of the road	Good
Comments	Construction finished
Duration of work	
Contact for Routine Road Maintenance	Wim Prinsloo 082 494 8947

On

National Route	R33 Section 8
Section	N17 to Carolina
Distance	
Description	
Condition of the road	Good
Comments	
Duration of work	Construction Finished
Contact for Routine Road Maintenance	Gustav Fouche 082 780 2391

National Route	R34
Section	Vryburg to Sweizer Reneke
Distance	61 km
Description	Single carriageway with gravel shoulders.
Condition of Road	Fair to poor. Last 30 km between Vryburg and Sweizer Reneke has narrow lane widths of 3 metre per lane – Shoulder work to improve lane width in progress
Comments	Declared as national road 28 on September 2012 – Previously a provincial road
Duration of Work	On going
Contact for Routine Road Maintenance	Frank Joubert 083 781 3676

National Route	R35
Section	Amersfoort over Bethal up to Middelburg
Distance	156 km
Description	Single carriageway with gravel shoulders.
Condition of the road	Fair to poor, Surface failures from Amersfoort to Morgenzon. It is very poor between Amersfoort and Morgenzon
Comments	Construction started in January 2012.
Duration of work	
Contact for Routine Road Maintenance	Kobus Vermeulen 082 304 6566

National Route	R35 Section 2
Section	Bethal to Middelburg
Distance	
Description	
Condition of the road	
Comments	
Duration of work	Construction started in January 2012
Contact for Routine Road Maintenance	

National Route	R36 – R71 – R526 – R40
Section	Bandelierskop –Soekmekaar –Mooketsi – Modjadjikloof (Duiwelskloof) – Tzaneen – Gravelotte – Mica – Klaserie (New Mpumalanga Border)
Distance	197 km
Description	Two-lane narrow single carriageway with gravel shoulders in places.
Condition of the road	Good.
Comments	Witrivier to Mica construction started.
Duration of work	
Contact for Routine Road Maintenance	Dries Grundlingh 083 269 3029

National Route	R36
Section	Tzaneen to Soekmekaar
Distance	
Description	
Condition of the road	
Comments	Reconstruction work – Stop/Go
Duration of work	Ongoing
Contact for Routine Road Maintenance	Bertie Brits 083 303 4418

National Route	R37
Section	Polokwane (Pietersburg) up to Mpumalanga border north of Burgersfort
Distance	160 km
Description	Single carriageway with gravel shoulders.
Condition of the road	Fair
Comments	Patching, Reseal shoulder work.
Duration of work	Routine Road Maintenance teams may be encountered. Patching
Contact for Routine Road Maintenance	George Brand 082 555 8493

National Route	R37
Section	Burgersfort to Lydenburg
Distance	57 km
Description	Single carriageway road with paved shoulders.
Condition of Road	Variable but generally fair.
Comments	In-Situ Recycling
Duration of Work	
Contact for Routine Road Maintenance	Dries Grundlingh 083 269 3029

National Route	R37
Section	Lydenburg over Sabie to Nelspruit
Distance	86Km
Description	Single carriageway road with narrow shoulders.
Condition of Road	Fair
Comments	Ongoing Routine Road Maintenance
Duration of Work	
Contact for Routine Road Maintenance	Dries Grundlingh 083 269 3029

National Route	R38
Section	Bethal to Hendrina
Distance	
Description	Single carriageway with gravel shoulders.
Condition of the road	Good
Comments	RRM Teams may be encountered
Duration of work	Ongoing
Contact for Routine Road Maintenance	Kobus Vermeulen 082 304 6566

National Route	R38
Section	Hendrina to Carolina
Distance	171km
Description	Single carriageway with gravel shoulders.
Condition of the road	Construction finished
Comments	RRM Teams may be encountered
Duration of work	
Contact for Routine Road Maintenance	Wim Prinsloo 082 494 8947

National Route	R38
Section	Carolina to Barberton
Distance	
Description	
Condition of the road	
Comments	Repair and Reseal work – Stop/Go from Carolina to Badplaas
Duration of work	October 2013
Contact for Routine Road Maintenance	Gustav 082 780 2391

National Route	R40
Section	White River to Hazyview
Distance	
Description	
Condition of the road	
Comments	Reseal work – Stop/Go
Duration of work	Ongoing
Contact for Routine Road Maintenance	Zaaid 082 810 4806

National Route	R40
Section	Hazyview to Bushbuck Ridge
Distance	
Description	
Condition of the road	
Comments	In-Situ recycling & overlay on road for 10 kilometre from turnoff at Graskop to Bushbuckridge. One Stop/Go will be encountered.
Duration of work	Ongoing
Contact for Routine Road Maintenance	Johan van Staden 082 303 7367

National Route	R40
----------------	-----

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered



Section	R533 to Hoedspruit
Distance	
Description	
Condition of the road	
Comments	Reseal work – Stop/Go
Duration of work	No construction
Contact for Routine Road Maintenance	Eugene 082 902 8047

National Route	R40
Section	Hoedspruit to Mica
Distance	
Description	
Condition of the road	
Comments	Reseal work – Stop/Go
Duration of work	No construction
Contact for Routine Road Maintenance	Johan 082 925 5261

National Route	R40
Section	North of White River to Klaserie (New Mpumalanga Border)
Distance	116 km
Description	Single carriageway with gravel shoulders in places.
Condition of Road	Fair
Comments	Construction started
Duration of Work	
Contact for Routine Road Maintenance	Dries Grundlingh 083 269 3029

National Route	R40
Section	Nelspruit to Barberton
Distance	45 km
Description	Upgraded single carriageway with climbing lanes in places and paved shoulders. Portion between Hilltop and Barberton still under construction, see2) below
Condition of Road	Very good and completed from Nelspruit to Hilltop Pass but fair to poor where construction work is still in progress towards Barberton. Road surfaces varying from well- kept gravel deviations to temporary all weather surfaces, but with no lane markings.
Comments	Construction completed. Now on the defect liability period.
Duration of Work	No construction
Contact for Routine Road Maintenance	Dries Grundlingh 083 269 3029

National Route	R49
Section	Mafikeng to Kopfontein Border
Distance	163 km
Description	Single carriageway with gravel shoulders.
Condition of Road	Fair to Good
Comments	Declared as national road on 28 September 2012 – Previously a provincial road
Duration of Work	Routine Maintenance On going
Contact for Routine Road Maintenance	Gerrit Mostert 079 492 8691

National Route	R56
Section	1, N9 Middleburg to Steynsburg
Distance	85km
Description	Two lane single carriage way
Condition of the road	Fair with isolated poor areas
Comments	4 months reseal project to commence in October 2013
Duration of work	
Contact for Routine Road Maintenance	Pottie Potgieter 082 566 7301

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

National Route	R56
Section	2, Steynsburg to Molteno
Distance	57km
Description	Two lane single carriage way
Condition of the road	Poor
Comments	Regular slow moving trucks with wind turbine components can be expected
Contact for Routine Road Maintenance	Pottie Potgieter 082 566 7301

National Route	R56
Section	3, Molteno to N6
Distance	35km
Description	Two lane carriage way
Condition of the road	Fair
Comments	
Contact for Routine Road Maintenance	Pottie Potgieter 082 566 7301

National Route	R56
Section	4, N6 to Dordrecht
Distance	35km
Description	Two lane single carriage way
Condition of the road	Fair
Comments	
Contact for Routine Road Maintenance	Pottie Potgieter 082 566 7301

National Route	R56
Section	5, Dordrecht to Indwe
Distance	38km
Description	Two lane single carriage way
Condition of the road	Fair
Comments	
Contact for Routine Road Maintenance	Pottie Potgieter 082 566 7301

National Route	R56
Section	6, Indwe to Elliot
Distance	56km
Description	Two lane single carriage way
Condition of the road	Fair to poor
Comments	
Duration of work	Ongoing
Contact for Routine Road Maintenance	Darlington Chakapfava 084 881 4306

National Route	R56
Section	7, Elliot to Maclear
Distance	68km
Description	Two lane single carriage way
Condition of the road	Fair
Comments	
Duration of work	Ongoing
Contact for Routine Road Maintenance	Darlington Chakapfava 084 881 4306

National Route	R56
Section	8, Maclear to Mt Fletcher
Distance	64km
Description	Two lane single carriage way
Condition of the road	Fair

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

Comments	
Duration of work	Ongoing
Contact for Routine Road Maintenance	Darlington Chakapfava 084 881 4306

National Route	R56
Section	9, Mt Fletcher to Matatiele
Distance	66km
Description	Two lane single carriage way
Condition of the road	Fair
Comments	
Duration of work	Ongoing
Contact for Routine Road Maintenance	Darlington Chakapfava 084 881 4306

National Route	R56
Section	10, Matatiele to Eastern Cape Border
Distance	37km
Description	Two lane single carriage way
Condition of the road	Fair to poor
Comments	
Duration of work	Ongoing
Contact for Routine Road Maintenance	Darlington Chakapfava 084 881 4306

National Route	R58
Section	1, Norvalspont to Venterstad
Distance	39km
Description	Two lane single carriage way
Condition of the road	Fair
Comments	
Duration of work	Ongoing
Contact for Routine Road Maintenance	Ofan Motlhakane 079 879 4720

National Route	R58
Section	2, Venterstad to Burgersdorp
Distance	58km
Description	Two lane single carriage way
Condition of the road	Fair
Comments	
Duration of work	Ongoing
Contact for Routine Road Maintenance	Ofan Motlhakane 079 879 4720

National Route	R58
Section	3, Burgersdorp to Aliwal North N6
Distance	55km
Description	Two lane single carriage way
Condition of the road	Good
Comments	
Duration of work	Ongoing
Contact for Routine Road Maintenance	Ofan Motlhakane 079 879 4720

National Route	R58
Section	4, Aliwal North N6 to Lady Grey
Distance	49km
Description	Two lane single carriage way
Condition of the road	Fair
Comments	

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

Duration of work	Ongoing
Contact for Routine Road Maintenance	Ofan Motlhakane 079 879 4720

National Route	R58
Section	Lady Grey to Barkley East
Distance	66km
Description	Two lane single carriage way
Condition of the road	Fair
Comments	
Duration of work	Ongoing
Contact for Routine Road Maintenance	Ofan Motlhakane 079 879 4720

National Route	R58
Section	Barkly East to Elliot
Distance	62km
Description	Two lane single carriage way
Condition of the road	Fair
Comments	
Duration of work	Ongoing
Contact for Routine Road Maintenance	Ofan Motlhakane 079 879 4720

National Route	R61
Section	1 ( East Cape/West Cape Border to Aberdeen)
Distance	74.5 km
Description	Single carriageway road
Condition of Road	Good
Comments	No construction but motorists may encounter occasional short term closures for routine maintenance. Motorists to be aware of wild animals.
Contact for Routine Road Maintenance	Christo Muller 83 628 0272

National Route	R61
Section	Bethesda (N9 Intersection) to Cradock (N10 Intersection)(section 2)
Distance	85.8 km
Description	A narrow 2-lane single carriageway with gravel shoulders over most of the length.
Condition of Road	Fair.
Comments	No construction but motorists may encounter occasional short term closures for routine maintenance
Contact for Routine Road Maintenance	Charmaine Diedreicks 083 508 9355

National Route	R61
Section	Cradock (N10 Intersection) to Tarkastad (section 3)
Distance	74.5 km
Description	A narrow 2-lane single carriageway with gravel shoulders
Condition of Road	0-24km Good 24-75kmFair
Comments	No construction but motorist may encounter occasional short-term closures over short sections for routine maintenance. Motorist to be aware of wild animals in rural areas and pedestrians in urban area at Cradock and Tarkastad.
Contact for Routine Road Maintenance	Charmaine Diedreicks 083 508 9355

National Route	R61
Section	Tarkastad to Queenstown (section 4)
Distance	63.1km
Description	A narrow 2 lane single carriageway with gravel shoulders.
Condition of Road	Fair.
Comments	Construction is in progress from over this whole section. A maximum of 3 Stop/Go operations will be encountered. Localised detours can be expected at bridges. Motorist are advised to am $\pm 1$ hour to journey time. Motorists to be aware of wild animals in rural areas and pedestrians in urban areas of Cradock and Queenstown.
Contact for Routine Road Maintenance	Charmaine Diedreicks 083 508 9355
Contact for Construction Work	Hermanus Botha 082 835 0415

National Route	R61
Section	Queenstown (N6) to Cofimvaba (Section 5)
Distance	60km
Description	A 2-lane single carriageway with wide paved shoulders
Condition of Road	Good
Comments	No construction but motorists may encounter occasional short-term closures over short sections for routine maintenance. Motorists to be aware of pedestrians and stray animals
Contact for Routine Road Maintenance	Riaan Graaf 082 821 0175

National Route	R61
Section	Cofimvaba to Engcobo (Section 6)
Distance	92 km
Description	Narrow 2 lane single carriageway with limited gravel shoulders.
Condition of Road	Fair to good.
Comments	Motorists to be aware of pedestrians and stray animals. Construction works are in progress in the Ngcobo area. Reduced speeds and localised detours can be expected. Motorists may encounter occasional short term closures on short section in this area. Road may also be closed for short durations due to blasting operation.
Duration of Work	
Contact for Routine Road Maintenance	Riaan Graaf 082 821 0175
Contact for Construction Work	Dennis Brown 082 331 7784

National Route	R61
Section	Engcobo to Mthatha (Section 7)
Distance	49 km
Description	Narrow 2 lane single carriageway with limited gravel shoulders.
Condition of Road	Fair to good
Comments	No construction but motorists may encounter occasional short-term closures over short sections for routine maintenance and construction works at the Mthatha airport and the R61/N2 Bypass intersections. Motorists to be aware of pedestrians and stray animals.
Contact for Routine Road Maintenance	Riaan Graaf 082 821 0175

National Route	R61
Section	Mthatha to Port St Johns (Section 8)
Distance	74 km
Description	A 2-lane single carriageway, with surfaced shoulders.
Condition of Road	Fair.
Comments	Construction works are in progress in town area. Road markings and minor seal repair are in progress. Motorist must also be aware of reduced speed limits of 60km/h are imposed through sections which require maintenance or minor repairs. Tombo upgrade commenced in October 2011. Traffic will be accommodated through a temporary by pass – reduced speed to 40km/h. Estimated completion November 2013., Traffic will be all through.
Duration of work	Estimate completion commenced November 2012-4

Contact for Routine Road Maintenance	Riaan Graaf 082 821 0175
Contact for Construction works	Dani Mecer 072 628 8001

National Route	R61 ( Wild Coast)
Section	Ntafufu River to Lusikisiki
Distance	18 Km
Description	Two-lane Single carriageway with Passing lanes
Condition of Road	Good
Comments	Motorist to be aware of pedestrians and animals. The road is winding. And motorists may encounter occasional short term closures on a short section for routine maintenance. Reseal in progress estimated completion December 2013. Over the winter period seal work has been done
Duration	Reseal to commence Oct 2011 ( $\pm$ 20km) Expect Stop-Go's-06 May completion date
Contact for Routine Road Maintenance	Riaan Graaf 082 821 0175
Contact for Construction	Dani Mercer 072 628 8001

National Route	R61
Section	Mtambvuna River (Provincial Boundary) to Port Shepstone
Distance	45 km
Description	Two-lane single carriageway with passing lanes.
Condition of Road	Good.
Comments	
Contact for Routine Road Maintenance	Amit Bhoora 082 442 9646

National Route	R62
Section	East Cape borders to N2
Distance	117km
Description	Single carriage road
Condition of Road	Fair but narrow width
Comments	
Contact for Routine Road Maintenance	Jaco klopper 083 446 8501

National Route	R63
Section	East Cape and Cape border to Graaff – Reinet
Distance	50km
Description	Single carriageway with gravel shoulders
Condition of Road	Fair but narrow over most of the section
Comments	
Contact for Routine Road Maintenance	Christo Muller 083 628 0272

National Route	R63
Section	N9 Graaff – Reinet to R75 junction ( to Pearson)
Distance	23km
Description	Single carriageway with paved shoulders
Condition of Road	Fair to Good
Comments	No construction normal RRM
Contact for Routine Road Maintenance	Sisanda Dyubhela 073 817 7939

National Route	R63
Section	R75 to N10
Distance	123km
Description	Two way single carriage way with gravel shoulders
Condition of Road	Fair
Comments	
Contact for Routine Road Maintenance	Sisanda Dyubhela 073 817 7939

National Route	R63
Section	N10 to Adelaide
Distance	78km
Description	Two way single carriage way with gravel shoulders. 4km section before Bedford in poor condition.
Condition of Road	Fair
Comments	
Contact for Routine Road Maintenance	Sisanda Dyubhela 071 873 9144

National Route	R63
Section	Adelaide to Komga
Distance	189km
Condition of Road	Fair
Comments	Two way single carriage way. Motorist may encounter occasional short closure. Between Fort Beaufort and Alice repairs and uneven surface will be encountered
Contact for Routine Road Maintenance	Thandiswa Bottoman 082 821 0175

National Route	R67
Section	Fort Beaufort to Whittlesea
Distance	54,45km
Description	Two-lane single carriage with passing lane
Condition of Road	Fair
Comments	Beware of pedestrian and animals observe speed limit though Nico Malan Pass
Contact for Routine Road Maintenance	Gert de Lange 076 413 2989

National Route	R67
Section	Whittlesea to R61 Queenstown
Distance	33,36km
Description	Two way lane single carriageway with gravel shoulders
Condition of Road	Fair
Comments	Beware of pedestrian and animal crossing
Contact for Routine Road Maintenance	Gert de Lange 076 413 2989

National Route	R67
Section	Grahamstown to Fort Beaufort
Distance	70.65km
Description	Two lane single carriageway with gravel shoulders
Condition of Road	Fair
Comments	The road is winding , observe speed limit though ECCA Pass beware of wild animals after dusk
Contact for Routine Road Maintenance	Gert de Lange 076 413 2989

National Route	R71
Section	Polokwane (Pietersburg) – Magoebaskloof – Tzaneen
Distance	89 kms
Description	Two-lane narrow single carriageway with gravel shoulders.
Condition of the road	Fair.
Comments	Construction started
Duration of work	Ongoing
Contact for Routine Road Maintenance	Dries Grundlingh

*Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered*

Maintenance	083 269 3029
National Route	R71 Section 1
Section	Polokwane to Boyne to Tzaneen
Distance	Km 6-39
Description	
Condition of the road	
Comments	Reseal work
Duration of work	Completed
Contact for Routine Road Maintenance	Dries Grundlingh 083 269 3029

National Route	R71 Section 2
Section	Tzaneen to Gravelotte
Distance	Km 0 – 52
Description	
Condition of the road	
Comments	Reseal work
Duration of work	Completed
Contact for Routine Road Maintenance	Dries Grundlingh 083 269 3029

National Route	R72
Section	Nanaga to Alexandria
Distance	50 km
Description	Two lane single carriageway with paved shoulders
Condition of the road	Good
Comments	
Duration of work	
Contact for Routine Road Maintenance	Ian Smith 084 415 2002

National Route	R72
Section	Alexandra – Peddie turnoff.
Distance	117km
Description	Two lane single carriageway with grave shoulders
Condition of the road	Fair but narrow width
Comments	
Duration of work	
Contact for Routine Road Maintenance	Ian Smith 084 415 2002

National Route	R72
Section	Peddie turn off to East London Airport
Distance	62km
Description	Two lane single carriageway with paved soulder
Condition of the road	Fair
Comments	
Duration of work	
Contact for Routine Road Maintenance	Ian Smith 084 415 2002

National Route	R75
Section	Port Elizabeth to Ultenhage North
Distance	28km
Description	Dual carriageway with 2 lanes per direction for the first 14 km. Not a freeway and a lot of level accesses exist, also a lot of pedestrian movements
Condition of the road	Good
Comments	Please take special care for first 14 km and normal RRM work
Duration of work	
Contact for Routine Road Maintenance	Jaco Klopper

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered



Maintenance	083 446 8501
National Route	R75
Section	Uitenhage North to Jansenville
Distance	136km
Description	A two-lane single carriageway with gravel shoulders
Condition of the road	Fair
Comments	No construction but motorists may encounter occasional short closures for routine road maintenance
Duration of work	
Contact for Routine Road Maintenance	Itumeleng Mokhele 082 421 5599

National Route	R75
Section	Jansenville to R63 junction (Pearston)
Distance	59km
Description	A two-lane single carriageway with covered shoulders last 23km with paved shoulders
Condition of the road	Fair there is construction work with a bypass for traffic for the rest of the road section
Comments	For + - 4km towards end before Pearson junction Normal RRM by pass not good
Duration of work	This construction almost done
Contact for Routine Road Maintenance	Itumeleng Mokhele 082 421 5599

National Route	R81
Section	Polokwane (Pietersburg) – Mooketsi – Giyani
Distance	80 km
Description	Two-lane narrow single carriageway with gravel shoulders.
Condition of the road	Fair.
Comments	Patching, Reseal shoulders.
Duration of work	Completed
Contact for Routine Road Maintenance	Dries Grundlingh 083 269 3029

National Route	R81
Section	Polokwane to Munnik
Distance	
Description	
Condition of the road	
Comments	Reconstruction work – Stop/Go
Duration of work	Completed
Contact for Routine Road Maintenance	Fanie Mini 082 775 0931

National Route	R101
Section	Middefontein Interchange (Modimole ( Nylstroom)) to Mookgopong (Naboomspruit)
Distance	30 km
Description	Two-lane single carriageway with passing lanes.
Condition of Road	Good.
Comments	Routine Road Maintenance teams may be encountered. Patching.
Duration of Work	
Contact for Routine Road Maintenance	George Brand 082 555 8493

National Route	R101
Section	Mookgopong (Naboomspruit) to Mokopane (Potgietersrust)
Distance	68km
Description	Two-lane single carriageway with paved shoulders and passing lanes in places.
Condition of Road	Fair
Comments	Routine Road Maintenance teams may be encountered. Patching.
Duration of Work	
Contact for Routine Road Maintenance	George Brand 082 555 8493

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

National Route	R101
Section	Mokopane (Potgietersrus) to southern outskirts of Polokwane (Pietersburg)
Distance	51km
Description	Two-lane single carriageway with paved shoulders and passing lanes in places.
Condition of Road	Fair
Comments	
Duration of Work	Routine Road Maintenance teams may be encountered. Patching.
Contact for Routine Road Maintenance	George Brand 082 555 8493

National Route	R104 (P154-1& P154-2)
Section	Pretoria-Bronkhorstspuit-Mpumalanga Border
Distance	64.28 Kms
Description	2-lane single carriageway with narrow gravel shoulders
Condition of the road	Fair/Poor uneven in places
Comments	Construction started
Duration of work	
Contact for Routine Road Maintenance	Obed Monare 072 746 9267

National Route	R300
Section	Swartklip Interchange to Stellenberg Interchange
Distance	16.1 km
Description	Three-lane dual carriageway with paved shoulders.
Condition of Road	Good
Comments	No construction works
Duration of Work	
Contact for Routine Maintenance	Heuppschenne Lekay 082 782 9155

National Route	R505
Section	Ottoshoop to Lichtenburg
Distance	50 km
Description	Two-lane single carriageway with gravel shoulders
Condition of the road	Fair to Good.
Comments	Declared as national road on 28 September 2012 – Previously a provincial road
Duration of work	No construction. Routine maintenance on-going
Contact for Routine Road Maintenance	Gerrit Mostert 079 492 8691

National Route	R510
Section	North West Border - Thabazimbi – Lephalala (Ellisras) – Monte Christo
Distance	253 km
Description	Two-lane single carriageway with gravel shoulders
Condition of the road	Good.
Comments	No construction
Duration of work	
Contact for Routine Road Maintenance	Stephan du Plessis 084 491 1165

National Route	R521
Section	Polokwane (Pietersburg) – Dendron - Vivo
Distance	103 km
Description	Two-lane single carriageway.
Condition of the road	Fair. Gravel shoulders.
Comments	Routine Road Maintenance teams may be encountered. Patching of edge breaks
Duration of work	
Contact for Routine Road Maintenance	George Brand 082 5558493

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

National Route	R523
Section	Vivo - Waterpoort – Masekwaspoort
Distance	75 km
Description	Two-lane single carriageway.
Condition of the road	Good
Comments	Routine Road Maintenance teams may be encountered. Patching of edge breaks
Duration of work	
Contact for Routine Road Maintenance	George Brand 082 5558493

National Route	R555
Section	Witbank to Middelburg
Distance	28 km
Description	A 2-lane single carriageway road with narrow gravel shoulders
Condition of Road	Fair
Comments	No construction.
Duration of work	
Contact for Routine Road Maintenance	Obed Monare 072 746 9267

National Route	R570 (P133/1)
Section	N4 to Malalane Gate
Distance	3 km
Description	Single carriageway with paved shoulders.
Condition of Road	Fair, uneven in places.
Comments	No construction.
Duration of work	
Contact for Routine Road Maintenance	Lesley Kaht 072 202 7632

National Route	R570 (P80/1)
Section	N4 to Jeppes Reef Border Post
Distance	41 km
Description	Single carriageway with gravel shoulders.
Condition of Road	Fair, but uneven in places.
Comments	No construction.
Duration of Work	
Contact for Routine Road Maintenance	Lesley Kaht 072 202 7632

National Route	R571 (D797)
Section	One Tree Hill (P80/1) to Tonga (D2948)
Distance	27 km
Description	Single carriageway with gravel shoulders.
Condition of Road	Fair to poor, and uneven in places.
Comments	No construction.
Duration of Work	
Contact for Routine Road Maintenance	Lesley Kaht 072 202 7632

National Route	R571 (D2683))
Section	N4 to Coopersdal
Distance	21 km
Description	Single carriageway with gravel shoulders.
Condition of Road	Fair, uneven in places
Comments	No construction.
Duration of Work	
Contact for Routine Road Maintenance	Lesley Kaht 072 202 7632

National Route	R571 (D2948)
Section	Tonga (D797) to Mangweni (P179/1)
Distance	10 km
Description	Single carriageway with paved shoulders.
Condition of Road	Fair to satisfactory.
Comments	No construction.
Duration of Work	
Contact for Routine Road Maintenance	Lesley Kaht 072 202 7632

National Route	R572
Section	Monte Christo – Tom Bourke
Distance	95 kms
Description	Two-lane single carriageway.
Condition of the road	Good
Comments	
Duration of work	Completed
Contact for Routine Road Maintenance	Stephan du Plessis 084 491 1165

## NATIONAL BORDER CONTROL POSTS

### Botswana Border

Border Post	Location	Description	Condition	Opening Times
Twee Rivieren	Situated in the Kgalagadi Cross Border National Park	Single carriageway gravelled road.	Fair	08h00 to 16h30
Gemsbok	Between Upington and Botswana	Single carriageway gravelled road.	Fair	08h00 to 16h30
Middelputs	Between Van Zylsrus and Botswana	Single carriageway gravelled road.	Fair	08h30 to 16h30
McCarthy's Rest	Route R380 between Kathu and Thshabon (Botswana)	Single carriageway gravelled road.	Fair	08h00 to 16h30
Makopong	Route R379 between Bryburg and Botswana	Single carriageway gravelled road.	Fair	07h30 to 16h00
Bray	Route R378 between Bryburg and Botswana	Single carriageway gravelled road.	Fair	07h30 to 16h00
Boshoek	Route R375 between Bryburg and Botswana	Single carriageway gravelled road.	Fair	07h30 to 16h00
Magobistad	Between Mafikeng & Botswana	Single carriageway gravelled road.	Fair	07h30 to 16h30
Ramatlabama	Between Mafikeng & Botswana	Single carriageway paved road.	Good	07h00 to 20h00
Skilpadshek	N4 Platinum – Lobatse	Single carriageway paved road.	Good	07h00 to 19h30
Swartkopfontein	Between Zeerust & Gaborone	Single carriageway paved road.	Good	07h00 to 19h00
Kopfontein	Between Zeerust & Gaborone	Single carriageway paved road.	Good	07h00 to 22h00
Derdepoort	Between Rustenburg & Botswana	Single carriageway gravelled road.	Poor	07h00 to 19h00
Stockpoort	From Ellisras to Botswana	Single carriageway paved road.	Good	08h00 to 16h00
Groblers Bridge	From Potgietersrus on N11 to Botswana	Single carriageway paved road.	Good	08h00 to 18h00
Zanzibar	Between Alldys & Selebi-Pikwi	Single carriageway gravelled road.	Fair	08h00 to 16h00
Platjan	Between Alldys & Selebi-Pikwi	Single carriageway gravelled road.	Fair	08h00 to 16h00
Pondrft	From Alldys on R521 to Botswana	Single carriageway paved road.	Good	08h00 to 16h00

### Namibia Border

Border Post	Location	Description	Condition	Opening Times
Alexander Bay	Between Alexander Bay and Oranjemund (Namibia)	Single carriageway paved road.	Good	06h00 to 22h00
Violsdrift	Route N7/B1 between Springbok and Keetmanshoop (Namibia)	Single carriageway paved road.	Good	24 hours
Onseepkans	Route R358/C10 between Pofadder and Karasburg	Single gravelled road with single traffic lane bridge over Orange River Bridge	Fair	08h00 to 16h30
Nakop	Route N10/B3 between Upington and Karasburg (Namibia)	Single carriageway paved road with gravelled shoulders. New Border Control Post situated 1 km from actual border with Namibia.	Good	24 hours
Noenieput	Between Upington and Aroab (Namibia)	Single carriageway gravelled road.	Fair	08h00 to 16h30
Rietfontein	Route R31/C16 between Askam and Aroab (Namibia)	Single carriageway gravelled road.	Fair	08h00 to 16h30

### Zimbabwe Border

Border Post	Location	Description	Condition	Opening Times
Beitbridge	On N1 between RSA and Zimbabwe	Single carriageway paved road.	Fair	Passengers: 24hrs Commercial: 24hrs

### Mozambique Border

Border Post	Location	Description	Condition	Opening Times
Pafuri	In Kruger National Park, nearest route is R525, east/west direction ±25 km adrift)	Single carriageway paved road under construction.	Fair	08h00 to 16h00
Lebombo	On N4 between Nelspruit and Maputo	Single carriageway paved road.	Good	06h00 to 22h00
Kosibay (Farazela)	On R22 between RSA and Mozambique	Single carriageway paved road with narrow paved shoulders.	Good	06h00 to 1800

### Swaziland Border

Border Post	Location	Description	Condition
Mananga	On R571 between Komatipoort and Swaziland	Single carriageway paved road.	Fair
Jeppe's Reef	On R570 between Malelane and Swaziland	Single carriageway paved road.	Good
Josefsdal	On R40 between Barberton and Piggs Peak	Single carriageway gravelled road.	Poor
Oshoek	On N17 between Ermelo and Manzini	Single carriageway paved road.	Good
Waverley	Off R33 between RSA and Swaziland	Single carriageway paved road.	Good
Nerston	On R65 between RSA and Swaziland	Single carriageway paved road.	Fair
Emhlatinhi	Between Piet Retief and Swaziland	Single carriageway paved road.	Good
Bothashoop	Between Piet Retief and Swaziland	Single carriageway gravelled road.	Fair
Mahamba	Between Piet Retief and Swaziland	Single carriageway paved road.	Good
Onverwacht	D1936 off N2 (KwaZulu-Natal)	Single carriageway paved road.	Good
Golela/Lavumisa	P 720 off N2 (KwaZulu-Natal)	Single carriageway paved road.	Good

Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered

**Lesotho Border**

Border Post	Location	Description	Condition
Monantsapas	R 57/S1579 (Free State)	Single carriageway paved road	Fair to good
Caledonspoort	P 92/1 (Free State)	Single carriageway paved road	Fair to poor
Ficksburg Bridge	R 26 / P75/1 (Free State)	Single carriageway paved road	Fair
Peka Bridge	S 388 / S 306 (Free State)	Single carriageway gravel road	Poor
Maseru Bridge	N8 (Free State)	Single carriageway paved road.	Fair
Van Rooyen's Gate	P66/1 (Free State)	Single carriageway paved road	Fair
Sepapu's Gate	S4 (Free State)	Single carriageway gravel road	Poor
Makhaleng Bridge	S2 (Free State)	Single carriageway gravel road	Very Poor
Telle Bridge	R 392 (from Sterkspruit in the Eastern Cape)	Single carriageway paved road.	Good
Ongeluksnek	Eastern Cape: Off R 56. Closest towns are Mount Fletcher and Matatiele	Gravel approach road.	Poor to very poor. Only suitable to 4x4 vehicles beyond the border post.
Qacha's Nek	Eastern Cape: Closest town Matatiele	Gravel approach road.	Poor
Ramaselitso Gate	Eastern Cape: Closest from Matatiele	Gravel approach road.	Poor
Sani Pass	P 318 (KwaZulu-Natal)	Gravel approach road	Fair but often only accessible to 4X4 vehicles beyond the border post.

**THE SOUTH AFRICAN NATIONAL ROADS AGENCY SOC LTD****Contact Details****Head Office**

48 Tambotie Avenue  
Val de Grace  
Pretoria, 0184  
Tel. 012 844 8000  
Fax 012 362 2117

**Northern Region**

38 Ida Street  
Menlo Park  
Pretoria, 0081  
Tel. 012 426 6200  
Fax 012 348 1680

**Eastern Region**

58 Van Eck Place  
Mkondeni  
Pietermaritzburg  
Tel. 033 392 8100  
Fax 033 386 6284 / 3365

**Southern Region**

NRA House  
Southern Life Gardens

*Please note that the information contained herein could be subject to change. Routine Maintenance and Emergency Teams may be encountered*

70 Second Avenue  
Newton Park  
Port Elizabeth  
Tel. 041 398 3200  
Fax 041 398 3222

**Western Region**

Parc du Cap  
Building 5  
Corner Mispel Street / Willie van Schoor Avenue  
Bellville 7530  
Tel. 021 957 4600  
Fax 021 946 1630

Website: [www.sanral.co.za](http://www.sanral.co.za)

E-mail: [info@nra.co.za](mailto:info@nra.co.za)

Fraud Hot Line: 0800204558